

HTE # 05-50013149

HAMILTON COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION

18001

OPERATIONS PERMIT

Name: (owner) COLIN HAYSON/GROUCHO HOMES New Installation Septic Tank Repair

Property Location: SR# 2030 McLEAN CH. CH. RD Nitrification Line Expansion

Subdivision BETHUNE PROP. Lot # B Tax ID # _____ Quadrant # _____

Contractor: GERALD TEMPLE Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 100 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other POLYSTYRENE AGGREGATE TRENCH

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field	No. of ditches <u>1</u>	exact length of each ditch <u>400</u> ft.	width of ditches <u>3</u> ft.	depth of ditches <u>18</u> in.
------------------------------	----------------------------	----------------------------------------------	----------------------------------	-----------------------------------

French Drain Required: _____ Linear feet

Date: 12/1/05

PERMIT NO. 22222

Inspected by: [Signature] RJ

* WELL NOT DUG
AT THIS TIME

