

HTE #: 08-5-20408RR

HARNETT COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH
307 CORNELIUS HARNETT BOULEVARD
LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: Elbert Maynard

Phone #: 910-980-2165

Address: Dunn, NC 28339

Name of Mobile Home Park or S/D: Holly Wells Lot 1

Name of Owner (if different): Holly Wells

Address of Owner (if different): 194 Pitt Rd. Erwin, NC 28339

Property Location (State Road name and #): Pitt

Purpose of Inspection: Repositioning of home


The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

1. the intended use of the septic system should change, and/or
2. the system should fail or malfunction, and/or
3. the owner or tenant of the property change, and/or
4. after six months

**BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM
DO NOT DRIVE OR PARK ON SEPTIC SYSTEM**

AUTHORIZATION OF EXISTING SYSTEM


Signature of Environmental Health Specialist

3/25/2009
Date