

# CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT



Name: (owner) DANNIE LEE BLACKMON  New Installation  Septic Tank  
Property Location: SR# 1229  Repairs  Nitrification Line  
Subdivision                      Lot #                       
TAX ID#                      Quadrant #                       
Contractor: Mike Ray Registration # 64  
Basement with Plumbing:  Garage:   
Water Supply:  Well  Public  Community  
Distance From Well:                      ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other                       
Size of tank: Septic Tank: 1000 gallons Pump Tank:                      gallons  
Subsurface Drainage Field No. of ditches 2 exact length of each ditch 100 ft. width of ditches 3 ft. depth of ditches 18-24 in.  
French Drain:                      Linear feet

PERMIT NO. 09094

Date: 5-12-84  
Inspected by: James E. Mahant  
Environmental Health Specialist



SR 1229