## HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

## **EXISTING SEPTIC SYSTEM INSPECTION**

NAME Conny Molanto	PHONE # 99-820.0894
ADDRESS 37 Rambion CN Benson	N.C. 27504
NAME OF MOBILE HOME PARK OR S/D	NEWDOW Rock MIHA
NAME OF OWNER (IF DIFFERENT)	
ADDRESS OF OWNER (IF DIFFERENT)	•
PROPERTY LOCATION: STATE ROAD NAM	EAND# SYLITGG WISE 21)
PURPOSE OF INSPECTION: SWM	H
The aforementioned site has been evaluated Environmental Health Section. At the time of system serving this site. If this system should any necessar	by the Harnett County Health Department inspection, there appeared to be a septic malfunction, the owner is responsible for

## THIS INSPECTION IS VOID IF:

- (1) the intended use of the septic system should change, and/or
- (2) the system should fail or malfunction, and/or
- (3) the owner or tenant of the property changes, and/or
- (4) after six months

## BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM

YSTEM
EM
1-2616
Date