

**COUNTY OF HARNETT**  
**Building Inspections Department**  
**Planning Services**

**Certificate of Compliance:** \_\_\_\_\_ **Occupancy:**

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Mansf 1x

Name: Jessy Franklin; Judy Tripp

Address: 112 Judy Francis Lane

Littleton NC 27546

Date: 5-31-16

Building Official: \_\_\_\_\_

**Permit Numbers**

Building: \_\_\_\_\_

Electrical: \_\_\_\_\_

Insulation: \_\_\_\_\_

Plumbing: \_\_\_\_\_

Mechanical: \_\_\_\_\_

MFG Home: 16 500 38010

ADDRESS : 112 JUDY FRANCES LN SUBDIV:  
 CONTRACTOR : PHONE :  
 OWNER : TRIPP JERRY FRANKLIN & JUDY PHONE :  
 PARCEL : 11-0651- - -0013- - -  
 APPL NUMBER: 16-50038010 CP MOBILE HOME PARK  
 DIRECTIONS : T/S: 02/12/2016 10:28 AM LBENNETT --  
 S. MAIN ST - L ON TRIPP RD - L ON  
 MATTHEWS RD - 2ND RIGHT JUDY FRANCES LN  
 TRIPPS MHP LOT#18

**STRUCTURE: 000 000 14X80 SWMH 4BDR 1998**

# BEDROOMS : 4.00 MOBILE HOME YEAR : 1998.00  
 PROPOSED USE : SFD SEPTIC - EXISTING? : EXIST

**PERMIT: CPSW 00 CP MOBILE HOME SINGLEWIDE**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
T501 01	3/14/16 3/14/16	BS DA	R*MOBILE HOME FOUND./ M. WALL VRU #: 002788166 T/S: March 14, 2016 08:59 AM BSUTTON Drain plumbing not installed and tested.
T501 02	3/29/16 3/29/16	DT DA	R*MOBILE HOME FOUND./ M. WALL VRU #: 002795078 T/S: 03/29/2016 12:04 PM DETAYLOR Install plumbing to all fixtures, and test drain lines to floor level
T501 03	4/27/16 4/27/16	DT DA	R*MOBILE HOME FOUND./ M. WALL VRU #: 002807329 If able please call 910-890-1626 when going to do the inspection- I will meet inspector there if that is allowed T/S: 04/27/2016 02:52 PM DETAYLOR Plumbing drain lines must be tested. If rear bathroom drains are covered then note that, if not, run drain lines to them. Called number given to set up a time to meet but got an automated message without voicemail.
T501 04	5/03/16 5/04/16	DT DA	R*MOBILE HOME FOUND./ M. WALL VRU #: 002810620 We got the balloon test plug and filled up pipes to sink level-Thank You T/S: 05/04/2016 09:00 AM DETAYLOR Rear bathroom not connected to drain lines. No stand pipe, if test is being done through the house, the house must be unlocked for inspection.
T501 05	5/10/16 5/10/16	DT AP	R*MOBILE HOME FOUND./ M. WALL VRU #: 002813541 It should be ready now - we replaced bath tub and plumbing in spare bathroom- drain plug is in place and pipes are full T/S: 05/10/2016 12:51 PM DETAYLOR
Z818 01	5/23/16 5/23/16	RB AP	PZ*ZONING INSPECTION VRU #: 002819787 T/S: 05/23/2016 02:15 PM RBAKER
A814 01	5/23/16 5/20/16	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002819779 112 JUDY FRANCES LN LILLINGTON 27546 T/S: 05/20/2016 10:36 AM SBENNETT
T507 01	5/31/16 <i>5/31/16</i>	TI <i>APB</i>	R*MANUFACTURED HOME FINAL VRU #: 002822419 Mr Taylor -I painted the front steps and my husband says I wasn't supposed to because you have to see if they are treated - the underside is not painted and you can see they are treated