

SITE/SOIL EVALUATION FOR ON-SITE WASTE WATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	2	2	2							
HORIZON 1 DEPTH		0-18									
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FK									
STRUCTURE	.1941(A)(2)	GR									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 2 DEPTH		18-24									
TEXTURE GROUP	.1941(A)(1)	SCL									
CONSISTENCE	.1941	FK									
STRUCTURE	.1941(A)(2)	GR									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 3 DEPTH		24-36									
TEXTURE GROUP	.1941(A)(1)	SC									
CONSISTENCE	.1941	Sk Thin									
STRUCTURE	.1941(A)(2)	SPR									
MINERALOGY	.1941(A)(3)	SASP									
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	32	32	32							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.4-375	.4-300	.4-225							