

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-5"	0-48"	0-48"											
TEXTURE GROUP	.1941(A)(1)	S	S	S											
CONSISTENCE	.1941		VFR	VFR											
STRUCTURE	.1941(A)(2)		G	G											
MINERALOGY	.1941(A)(3)		NS/NP	NS/NP											
HORIZON 2 DEPTH		5"													
TEXTURE GROUP	.1941(A)(1)	C													
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)	EX/EP													
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942	5"	36"	36"											
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943, 1956														
CLASSIFICATION	.1948	U3	P3	P3											
LONG TERM ACCEPTANCE RANGE	.1955		1	1											

