

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		C-3	G-36								
TEXTURE GROUP	.1941(A)(1)	SL	C								
CONSISTENCE	.1941	VE	IF								
STRUCTURE	.1941(A)(2)	G	SL								
MINERALOGY	.1941(A)(3)	NG	SEP								
HORIZON 2 DEPTH		2-36									
TEXTURE GROUP	.1941(A)(1)	C									
CONSISTENCE	.1941	F									
STRUCTURE	.1941(A)(2)	SL									
MINERALOGY	.1941(A)(3)	SEP									
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	PS	AS								
LONG TERM ACCEPTANCE RANGE	.1955	3	3								



①

②

