

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-12	0-24	0-25							
Texture Group	.1941(A)(1)	LS	LS	LS							
Consistence	.1941	VFR									
Structure	.1941(A)(2)	G									
Mineralogy	.1941(A)(3)	NSWP									
HORIZON 2 DEPTH		12-22	24-30	25-38"							
Texture Group	.1941(A)(1)	SL	SL	SCL							
Consistence	.1941	FR									
Structure	.1941(A)(2)	CL/SL									
Mineralogy	.1941(A)(3)	SS/SL									
HORIZON 3 DEPTH		22"	30"								
Texture Group	.1941(A)(1)	PM	SCL								
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942										
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	U3	P5	P5							
LONG TERM ACCEPTANCE RATE	.1955		.5	.5							

3x70 @ 18"-24"  
= REPAIR

