

HTE 03-5-7235

16524

# OPERATIONS PERMIT

Name: (owner) Palm Harbor Home  New Installation  Septic Tank  
 Property Location: SR# 1100 (Bramble Hill Rd)  Repairs  Nitrification Line  
 Subdivision \_\_\_\_\_ Lot # 7  
 Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_  
 Contractor: Elvis Fancher Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community

Distance From Well: \_\_\_\_\_ ft.

**Following are the specifications for the sewage disposal system on above captioned property.**

Type of system:  Conventional  Other \_\_\_\_\_

Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field No. of ditches 1 exact length of each ditch 360 ft. width of ditches 3 ft. depth of ditches 1824 in.

French Drain Required: \_\_\_\_\_ Linear feet

Date: 12-11-03

Inspected by: Joe Wiles  
Environmental Health Specialist

PERMIT NO. 19432

