

HTE 04-5-9512

HAMILTON COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION

16551

OPERATIONS PERMIT

Name: (owner) SUGGS, DONALD & DELORIS New Installation Septic Tank
 Property Location: SR# DEES ST Repairs Nitrification Line
 Subdivision MANOR HILLS Lot # _____
 Tax ID # _____ Quadrant # _____
 Contractor: GERALD TEMPLE Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 100 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field	No. of ditches <u>1</u>	exact length of each ditch <u>240</u> ft.	width of ditches <u>3</u> ft.	depth of ditches <u>18-24</u> in.
------------------------------	----------------------------	--	----------------------------------	--------------------------------------

French Drain Required: _____ Linear feet

Date: 9/2/2007

Inspected by: Bryan McSwain R.S.
Environmental Health Specialist

PERMIT NO. 20831

