

HTE # Attempt To Repair

OPERATIONS PERMIT

Name: (owner) Joseph & Kathy Dwyer New Installation Septic Tank Repair

Property Location: SR# NC 24 (Calvin Rd) Nitrification Line Expansion

Subdivision Cameron Hill Lot # 26027 Tax ID # _____ Quadrant # _____
Concord

Contractor: Larry Sharpe Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other Pump to Tire chips

Size of tank: Septic Tank: 1000 gallons Pump Tank: 1000 gallons

Subsurface Drainage Field No. of ditches 1 exact length of each ditch 300 ft. width of ditches 3 ft. depth of ditches 18.24 in.

French Drain Required: _____ Linear feet Date: 5-10-05

PERMIT NO. 21545 Inspected by: J. W. A. R.

