

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner:
Address:
Proposed Facility:
Location of Site:
Water Supply: ☒ Public ☐ Individual ☒ Well
Evaluation Method: ☒ Auger Boring ☐ Pit
Type of Wastewater: ☒ Sewage ☐ Industrial Process

Applicant:
Date Evaluated:
Property Size:
Property Recorded: ☐ Spring ☐ Other
☐ Cut
☐ Mixed

1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY 1941		OTHER PROFILE FACTORS				Profile Class & LTAR
		1941 Structure/ Texture	1941 Consistence Mineralogy	1942 Soil Wetness/ Color	1943 Soil Depth (IN.)	1956 Sapro Class	1944 Restr Horiz	
49% WS	0-15	G-LS	VE NSNP					PS.3
	15-38	SBK/C	F: SSSP					
	38-4	pm						
	0-16	G-LS	VE NSNP					PS.3
	16-40	SBK/C	F: SSSP					
	0-19	G-LS	VE NSNP					PS.35
	19-36	SBK/SCI	F: SSSP					

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	CS	CS
Site LTAR	3	3

Other Factors (.1946): _____
Site Classification (.1948): PS
Evaluated By: Bm
Others Present:


COMMENTS: _____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE	I	S-SAND	1.2 - 0.8	VFR-VERY FRIABLE	NS-NON-STICKY
S-SHOULDER SLOPE		LS-LOAMY SAND			
L-LINEAR SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FR-FRIABLE	SS-SLIGHTLY STICKY
FS-FOOT SLOPE		L-LOAM			
N-NOSE SLOPE	III	SI-SILT-	0.6 - 0.3	FI-FIRM	S-STICKY
H-HEAD SLOPE		SIL-SILT LOAM			
CC-CONCLAVE SLOPE	IV	CL-CLAY LOAM	0.4 - 0.1	VFI-VERY FIRM	VS-VERY STICKY
CV-CONVEX SLOPE		SCL-SANDY CLAY LOAM			
T-TERRACE		SIC-SILTY CLAY		EFI-EXTREMELY FIRM	NP-NON-PLASTIC
FP-FLOOD PLAN		C-CLAY			
		SC-SANDY CLAY			SP-SLIGHTLY STICKY
					P-PLASTIC
					VP-VERY PLASTIC

STRUCTURE
 SG-SINGLE GRAIN
 M-MASSIVE
 CR-CRUMB
 GR-GRANULAR
 SBK-SUBANGULAR BLOCKY
 ABK-ANGULAR BLOCKY
 PL-PLATY
 PR-PRISMATIC

MINERALOGY
 SLIGHTLY EXPANSIVE
 EXPANSIVE

Show profile locations and other site features (dimensions, reference or benchmark, and North).



well located
any sketch of this

