

HTE # 05-50013273RR

OPERATIONS PERMIT

Name: (owner) SHERNITA KELLY New Installation Septic Tank Repair

Property Location: SR# 1244 MOORE'S CHAPEL RD Nitrification Line Expansion
Subdivision SPRING HILLS/D Lot # 2 Tax ID # _____ Quadrant # _____

Contractor: T & S DENNING FARMS Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 100 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other POLYSTYRENE AGGREGATE TRENCH

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons


Subsurface Drainage Field No. of ditches 1 exact length of each ditch 350 ft. width of ditches 3 ft. depth of ditches 18-20 in.

French Drain Required: _____ Linear feet

Date: 1/25/06

PERMIT NO. 22461

Inspected by: [Signature] RS



DRAWING
NTS

SR 1244