HTE#10-5-25778


Harnett County Department of Public Health

Improvement Permit

26379

.

A DUNDING PERMIT CANNOT DE ISSUED WITH ONLY AN IMPROVEMENT PERMIT
ISSUED TO: AOVANTAGE PLUS HOUSING SUBDIVISION LOT # 2
NEW REPAIR EXPANSION Site Improvements required prior to Construction Authorization Issuance:
Type of Structure: Moo (3227) 6)
Proposed Wastewater System Type: CONVENTIONAL
Projected Daily Flow: GPD
Number of bedrooms: <u>3</u> Number of Occupants: <u>6</u> max
Basement 🗆 Yes 🙀 No
Pump Required: 🗆 Yes 📉 No 🛛 🗆 May be required based on final location and elevations of facilities
Type of Water Supply: \Box Community 🖄 Public \Box Well Distance from well <u>$u \circ \circ$</u> feet Permit valid for: 💢 Five years
Permit conditions: 🗌 No expiration
Authorized State Agent:: SEE ATTACHED SITE SKETCH
The issuance of this permit by the Health Department in no way guarantees the issuance of other permits. The permit holder is responsible for checking with appropriate governing bodies in meeting their requirements. This site is subject to revocation if the site plan, plat, or the intended use changes. The Improvement Permit shall not be affected by a change in ownership of the site. This permit is subject to compliance with the provisions of the Laws and Rules for Sewage Treatment and Disposal and to conditions of this permit.
Construction Authorization
(Required for Building Permit)
The construction and installation requirements of Rules .1950, .1952, .1954, .1955, .1956, .1957, .1958. and .1959 are incorporated by references into this permit and shall be met. Systems shall be installed in accordance with the attached system layout.
ISSUED TO: <u>ADVANSAGE RLUS HOUSING</u> PROPERTY LOCATION: <u>NC24]27</u> SUBDIVISION LOT # 2
Facility Type: Moo(32276) Image: SUBDIVISION Image: Lot # _2 Facility Type: Moo(32276) Image: New Expansion Image: Repair
Basement? 🗆 Yes 🖂 No Basement Fixtures? 🗆 Yes 🖄 No
Type of Wastewater System** <u>Conventional</u> (Initial) Wastewater Flow: <u>480</u> GPD
(See note below, if applicable 🗆)
CONVENTIONAL (Repair)
Installation Requirements/Conditions Number of trenches
Septic Tank Size Existing gallons Exact length of each trench 50 feet Trench Spacing: Feet on Center
Pump Tank Size gallons Trenches shall be installed on contour at a Soil Cover: inches
Maximum Trench Depth of: CURSEN LINE inches (Maximum soil cover shall not exceed
(Trench bottoms shall be level to $+/-1/4$ " 36" above the trench bottom)
in all directions)
Pump Requirements:ft. TDH vs GPM inches below pipe
Aggregate Denth inches above nine
Conditions: 50 FOOT OF DEPIN LINE TO BE ADOED TO END OF
Conditions: 50 FOOT OF DEALN LINE TO BE ADOED TO END OF inclusions above pipe inclusions total inclusion to the constant of
NATER LINES (INCLUDING IRRIGATION) MUST BE 10FT. FROM ANY PART OF SEPTIC SYSTEM OR REPAIR AREA. No utilities allowed in initial or repair drain field area.
**If applicable: I understand the system type specified is different from the type specified on the application. I accept the specifications of this permit.
Dwner/Legal Representative Signature: Date:
Dwner/Legal Representative Signature: Date:
Construction Authorization is subject to compliance with the provision of the Laws and Rules for Sewage Treatment and Disposal and to the conditions of this permit.
Authorized State Agent: Date: Date: Construction Authorization Expiration Date:2_0315
Construction Authorization Expiration Date:2_315



いしっかしつ

SOIL EVALUATION REPORT

Date: 10/25/10

Owner: Russell W. Gilchrist and wife Odile J. Gilchrist

Location: NC HWY 24/27 Harnett County, NC

Project: Subdividing 11.02 acre Tyner Tract into three lots.

A site evaluation was conducted on a 11.02 acre tract for Mr. Russell J. Gilchrist located on NC hwy 24/27 in Harnett County, NC. The purpose of the site evaluation was to determine soil suitability for subsurface sewage disposal. Harnett County public water is available to the proposed lots.

Lot Numbers One and Three

The site evaluation conducted on lot numbers one and three identified an area of suitable soil that should be sufficient for the initial system and repair of a conventional septic system for a four bedroom home. Soil profiles augured across the lots indicated 48" of loamy sand to sandy loam soil. The LTAR should range from .7g/ft to .8 g/ft, and the slope ranges from 3% to 5%.

Lot Number Two

Lot number two currently has a doublewide mobile home with an existing well and septic system. The original septic system permit could not be located by the Harnett County Health Department. The septic tank was uncovered and a 3 ft. X 150 ft. drain line was probed out and flagged. A small storage building is located on the edge of the septic tank and should be moved to at least 5 ft. from the tank. The tank should be pumped, the "tee" and the pipe leading from the tank to the drain line checked.

The existing drain line is located at least ten feet from the proposed property line of lot two and three. Sufficient area of suitable soil was located for the expansion and repair of a conventional septic system for a four bedroom home. Soil profiles indicated 48" of sandy loam to loamy sand soil with an application rate of .7g/ft to .8 g/ft. The slope ranges from 3% to 5%.

These determinations were made in accordance with 15A NCAC 18A .1900 Laws and Rules for Sewage Treatment and Disposal Systems. Due to variations in citing specific uses, and potential for changes in regulations or soil conditions, issuance of an Improvement Permit by the Harnett County Health Department is not guaranteed.

Report submitted by:

anne Shadleton

James Shackleton REHS ECS/Environmental Consulting Service 3689 Buckhorn Road Sanford,NC27330 919-258-5310

Jung Garbons

Jerry Yarborough LSS

