

**SOIL/SITE EVALUATION
 for ON-SITE WASTEWATER SYSTEM**

Owner: Applicant: *Promer*
 Address: Date Evaluated:
 Proposed Facility: *man* Design Flow (.1949): *4.80*
 Location of Site: Property Recorded:
 Water Supply: ☒ Public ☐ Individual ☐ Well ☐ Spring ☐ Other
 Evaluation Method: ☐ Auger Boring ☐ Pit ☐ Cut
 Type of Wastewater: ☒ Sewage ☐ Industrial Process ☐ Mixed

P R O F I L E #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1	<i>L 5%</i>	<i>0-18</i>	<i>SL</i>	<i>fin gran swp</i>					
		<i>18-44</i>	<i>SL-clay</i>	<i>fin 1/2 s.s.p</i>	<i>40-42"</i>				<i>4</i>
2	<i>L-57%</i>	<i>0-20</i>	<i>SL</i>						
		<i>20-27</i>	<i>SL-clay</i>		<i>Rock sat 26-27"</i>				
3	<i>L 57%</i>	<i>0-20</i>	<i>SL</i>	<i>fin gran swp</i>					
	<i>L-57</i>	<i>20-44</i>	<i>SL</i>	<i>fin 1/2 s.s.p</i>					
4	<i>L 6-20</i>	<i>0-20</i>	<i>SL</i>	<i>Rock</i>	<i>Rock</i>				
5	<i>L 5%</i>	<i>0-18</i>	<i>SL</i>	<i>fin gran swp</i>					
	<i>L 5%</i>	<i>18-40</i>	<i>SL</i>	<i>fin 1/2 s.s.p</i>	<i>40"</i>				<i>4</i>
6	<i>L 10%</i>	<i>0-40</i>	<i>SL</i>						
		<i>40-48</i>	<i>SL</i>		<i>—</i>				<i>5</i>

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948): Evaluated By: <i>125</i> Others Present: <i>2</i>
Available Space (.1945)			
System Type(s)	<i>25%</i>	<i>25%</i>	
Site LTAR	<i>.4</i>	<i>.4</i>	

