Department of Environment, Health and Natural Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: Clayton
Address: Date Evaluated: 8-19-15
Proposed Facility: SFD Design Flow (.1949): 720 Property Size:
Location of Site: Property Recorded:
Water Supply: ☑ Public ☐ Individual ☐ Well ☐ Spring ☐ Other
Evaluation Method: ☑ Auger Boring ☐ Pit ☐ Cut
Type of Wastewater: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1,	L-2	0-18	SL	FR GRANULAR					
		18-44	SL-CLAY	FR SBK SBP	42"				.3
2,3	L-22	0-15	SL	FR GRANULAR					
		15-44	SC-CLAY	FR SBK SBP	40"-42"	3.6			.3
4	L-4	0-18	SL	FR GRANULAR					
		18-44	SC-CLAY	FR SBK SBP	38"-40"	3.1			.3

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	2BR	PPBR
Site LTAR	.3	.3

Other Factors (.1946):
Site Classification (.1948): 3
Evaluated By:
Others Present: