

RJB, P.E., P.A.

C-0269

ROBERT J. BRACKEN  
ENGINEER + SURVEYOR

3768 Carbonton Road • Sanford, North Carolina 27330  
(919) 774-6074 • bjbracken@windstream.net

April 18, 2016

Harnett County Building Inspections  
P.O. Box 65  
Lillington, NC 27546

REF: Residence @  
653 Morrison Rd.  
Lillington, NC  
Country Fair. Contractor

Dear Sir/Madam,

I made an onsite visit to the above referenced residential building site on or about April 12, 2016. The purpose of the visit was to observe the soft soil in the footing trench. I recommended that the contractor remove 36 inches of the soft soil and back fill with compacted stone, and place 2) # 4 rebar in the trench as per my directions. The excavation, placement of stone and rebar were done as per my instructions. The footing will support the live and dead loads required by the N.C. Residential Building Code 2012 Edition.

If you have any questions, please give me a call at 919-774-6074.

*Robert J. Bracken*

Robert J. Bracken, PE

RJB:jeb

