

COUNTY OF HARNETT
Building Inspections Department
Planning Services

Certificate of Compliance: _____ **Occupancy:** X

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Residential

Name: Karen Barkin

Address: 183 Stonemason Dr
Holly Springs, NC 27540

Date: 8-5-16

Building Official: _____

Permit Numbers

Building: _____

Electrical: _____

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

1650038527

[Signature]

ADDRESS : 183 STONEMASON DR
CONTRACTOR :
OWNER : LARKIN KAREN
PARCEL : 05-0626- - -0048- -11-
APPL NUMBER: 16-50038567 CP MODULAR HOME
DIRECTIONS : T/S: 04/28/2016 08:16 AM DJOHNSON --
42 FROM FUQUAY TOWARD DUNCAN GO APPROX
9 MILES, STONE MASON DR ON LEFT.
LAND NOTES : BPMN 5/18/16 PER LIZ GARCIA AT PU CUSTOMER WILL BE
REQUIRED TO PAY \$1725.00 FOR A NEW TAP.

STRUCTURE: 000 000 28X52 3 BR NO DECKS, PORCHES, GRGE OFF FRM
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW WATER SUPPLY : COUNTY

PERMIT: CPMH 00 CP MODULAR

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/10/16 6/10/16	KS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002828317 T/S: 06/08/2016 03:01 PM LBENNETT T/S: 06/10/2016 03:34 PM KSLATTUM
B103 01	6/22/16 6/22/16	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 002834188 T/S: June 22, 2016 11:53 AM BSUTTON
A814 01	6/27/16 6/24/16	SB AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002836401 183 STONEMASON DR HOLLY SPRINGS 27540 T/S: 06/24/2016 04:03 PM SBENNETT
B119 01	6/28/16 6/28/16	BS AP	R*MOD MARRIAGE WALL TIME: 17:00 VRU #: 002836849 T/S: 06/27/2016 10:40 AM JFORBES T/S: June 28, 2016 09:23 AM BSUTTON
H824 01	7/07/16 7/07/16	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002841575 T/S: 07/08/2016 11:51 AM SSTEWARD T/S: 07/08/2016 11:51 AM SSTEWARD
R425 01	7/28/16 7/28/16	BS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002849974 T/S: 07/27/2016 12:39 PM LBENNETT T/S: July 28, 2016 09:21 AM BSUTTON Plumbing is improperly supported, has reverse fall in portions of the main drain, and there is no water on the standpipe.
R425 02	7/29/16 7/29/16	BS DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002850527 T/S: 07/28/2016 01:21 PM LBENNETT T/S: July 29, 2016 10:51 AM BSUTTON Not ready. Plumber still working.
R425 03	8/01/16 8/01/16	BS AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002851038 T/S: 07/29/2016 03:35 PM DJOHNSON T/S: August 01, 2016 09:26 AM BSUTTON
R429 01	8/03/16 8/03/16	BS DA	FOUR TRADE FINAL TIME: 17:00 VRU #: 002851822 LOCK BOX CODE 4610 T/S: August 03, 2016 08:55 AM BSUTTON 1. Install crawlspace doors. 2. Uncover ground rods for inspection. 3. No expansion tank or pressure reducing valve found on main water line. 4. Pipe water heater T&P valve to exterior of foundation.
R429 02	8/05/16 <u>8/5/16</u>	TI <u>AP DJ</u>	FOUR TRADE FINAL TIME: 17:00 VRU #: 002853851 T/S: 08/04/2016 01:38 PM JFORBES