Department of Environment, Health and Natura Division of Environmental Health
On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:			
Address:	Date Evaluated:	100	
Proposed Facility: 3 8000	Design Flow (.1949): 360703	Property Size:	
Location of Site:	Property Recorded:		
Water Supply: Pu	blic Individual Well	☐ Spring	Other
Evaluation Method: Auger Borin	ng Pit Cut		
Type of Wastewater:	ewage Industrial Process	☐ Mixed	

P R O F I	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
کل		0-12	65						
		12	58x €		10727/2e/6"				VS
5		048	63	אין בע ששע					* 5g
		0-36	6,	97/20 AL					
		36-48	3876 SCL	177 25/4P					. 22_

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	J	ĺ	Evaluated By:
System Type(s)	CUN	60mb COU	Others Present:
Site LTAR	.22	.55	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 IV C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY PR-PRISMATIC

Show profile locations and other site features (dimensions, references or benchmark, and North)

