

SITE/ SOIL EVALUATION FOR ON-SITE WASTEWATER


APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-8	0-11	0-28"	0-48"						
Texture Group	.1941(A)(1)	FILL		S	S						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 2 DEPTH		8"									
Texture Group	.1941(A)(1)	SC/SL									
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	8"	0"	48"	42						
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	U3	U5	P3	P5						
LONG TERM				18	.8						
ACCEPTANCE RATE	.1955										

- ① BLACK SOIL @ 8"
CASEY
- ② B/G @ 0"

SEPTIC SYSTEM DESIGNED
FOR 3 BEDROOM HOUSE AS
REQUESTED BY APPLICANT



CROSS UTILITY LINES

5' 1/2"