

Old#  
HTE # 03-5-6194R  
New# 06-5-14878

# OPERATIONS PERMIT

Name: (owner) Eugene Erthe Chase III / Lee Brown  New Installation  Septic Tank  Repair

Property Location: SR# 1481  Nitrification Line  Expansion  
Subdivision \_\_\_\_\_ Lot # \_\_\_\_\_ Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_

Contractor: Maples Septic Tank Service Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community  
Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other Disk 4 Chamber


Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field No. of ditches 5 exact length of each ditch 80 ft. width of ditches 3 ft. depth of ditches 24 in.

French Drain Required: \_\_\_\_\_ Linear feet Date: 5/24/2006

PERMIT NO. 19757 Inspected by Dave McJannet, R.S.

\* Water line to be no closer than 10 ft. to any part of septic system



SR 1481