Department of Environment, Health and Natural Resources
Division of Environmental Health
On-Site Wastewater Section

Sheet:
Property ID:
Lot #:
File #:
Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address:
Proposed Facility: moved Home
Location of Site: SR 1532 MABREY
Date Evaluated: 5-16-11
Design Flow (.1949): 240
Property Recorded:
Property Size:
Water Supply: ☐ Public ☐ Individual ☑ Well ☐ Spring ☐ Other
Evaluation Method: ☑ Auger Boring ☐ Pit ☐ Cut
Type of Wastewater: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
1	L 3%	0-18	SL	FR GR NSNP					
		18-42	SC-CLAY	FM/M SBK S.P.	38"-40" 7.5YR 4/2				.4
2	L 3%	0-8	SL	FR GR NSNP					
		8-36	SC-CLAY	FM/M SBK S.P.	36" 7.5YR 4/2				.35
3	L 4%	0-10	SL	FR GR NSNP					
		8-30	SC CLAY	FM/M SBK S.P.	26-28" 7.5YR 4/2				.3

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	250 gp	250 gp
Site LTAR	.35	.3

Other Factors (.1946):
Site Classification (.1948): PG
Evaluated By:
Others Present: