

SOIL/SITE EVALUATION  
for ON-SITE WASTEWATER SYSTEM

Property ID:  
Lot #:  
File #:  
Code:

Owner:

Applicant: 2021

Date Evaluated: 6/24/08

Proposed Facility: SFD Design Flow (1949): 450

Property Size:

Location of Site:  
Water Supply:  Public  Individual  Well  
Evaluation Method:  Auger Boring  Pit  
Type of Wastewater:  Sewage  Industrial Process

Property Recorded:  
 Spring  Other  
 Cut  
 Mixed

PROFILE #	1940 Landscape Position/Slope%	SOIL MORPHOLOGY 1941		OTHER PROFILE FACTORS			Profile Class & LTAR	
		1941 Horizon Depth (IN.)	1941 Structure/Texture	1941 Consistence Mineralogy	1942 Soil Wetness/Color	1943 Soil Depth (IN.)		1944 Restr. Horiz.
1	L 5%	0-6 SL		fm GR NSNP				.3
		6-36 SC-clay		fm-15%us.P	28" 2.5% 42			
2	L 4-5%	0-10 SL		fm GR NSNP				.3
		10-36 SC-clay		fm-15%us.P	32" 2.5% 42			
3	L 4-5%	0-10 SL		fm GR NSNP				.3
		10-36 SC-clay		fm-15%us.P	32" 2.5% 42			
4	L 4-5%	0-12 SL		fm GR NSNP				.3
		12-36 SC-clay		fm-15%us.P	32" 2.5% 42			

Description	Initial System	Repair System
Available Space (.1945)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
System Type(s)	25% <sub>2</sub>	25% <sub>3</sub>
Site LTAR	.3	.3

Other Factors (.1946):

Site Classification (.1948): PS

Evaluated By: [Signature]

Others Present:

TRIANGLE SOUTH INDUSTRIAL PARK SUBDIVISION  
 DEED BOOK 2350, PAGE 429  
 DEED BOOK 2380, PAGE 331  
 MAP BOOK 8, PAGE 103  
 MAP BOOK 22, PAGE 78  
 LOT 3

*\*NEED SITE PLAN WITH SETBACKS + Report!*

*\*STAIRS W/BI BE NEEDED!*

REEK FARMS  
 1507, PG. 390  
 8, PAGE 103  
 22, PAGE 78

*pond*

*50' off pond*

*3x113 20-18*  
*R&B*  
*REPAIR*  
*25' 20*

SEPTIC TANK AND DRAIN FIELD BY OTHERS

DUMPSTER W/FENCE SURROUND

7200 SF

TRIANGLE SOUTH INDUSTRIAL PARK SUBDIVISION  
 DEED BOOK 2350, PAGE 429  
 DEED BOOK 2380, PAGE 331  
 MAP BOOK 8, PAGE 103  
 MAP BOOK 22, PAGE 78  
 LOT 3

*TRAPED  
 TRATED  
 TRASH  
 TRUNCATED  
 DRAIN  
 AREA*

DISTURBED AREA = 40,112 SQ. FT.

DEVELOPMENT SITE OWNER'S REQUIREMENTS

