# SITE/SOIL EVALUATIO.. FOR ON-SITE WASTE..ATER

| FACTORS | | PROFILES | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
| LANDSCAPE POSITION | .1940 | | | | | | | | | | |
| SLOPE (%) | .1940 | | | | | | | | | | |
| HORIZON 1 DEPTH | | 0-10" | 0-6" | 0-12" | 0-8" | 0-10" | 0-6" | | | | |
| TEXTURE GROUP | .1941(A)(1) | SL | SL | SL | SL | SL | SL | | | | |
| CONSISTENCE | .1941 | VFR | VFR | VFR | VFR | VFR | | | | | |
| STRUCTURE | .1941(A)(2) | G | G | G | G | G | | | | | |
| MINERALOGY | .1941(A)(3) | ~~NS/NP~~ NS/NP | NS/NP | NS/NP | NS/NP | NS/NP | | | | | |
| HORIZON 2 DEPTH | | ~~SCL~~ 10"+ | 6"-18" | 12-34" | 8-18" | 10-30" | 6"+ | | | | |
| TEXTURE GROUP | .1941(A)(1) | SCL | SCL | ~~SCL~~ w/ GRAVEL | SCL | C | SCL | | | | |
| CONSISTENCE | .1941 | FR | FR | FR | FR | FR | FR | | | | |
| STRUCTURE | .1941(A)(2) | SBK | SBK | SBK | SBK | SBK | SBK | | | | |
| MINERALOGY | .1941(A)(3) | S/P | S/P | S/P | S/P | S/P | S/P | | | | |
| HORIZON 3 DEPTH | | | | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | | | | | | | | | | |
| CONSISTENCE | .1941 | | | | | | | | | | |
| STRUCTURE | .1941(A)(2) | | | | | | | | | | |
| MINERALOGY | .1941(A)(3) | | | | | | | | | | |
| HORIZON 4 DEPTH | | | | | | | | | | | |
| TEXTURE GROUP | .1941(A)(1) | | | | | | | | | | |
| CONSISTENCE | .1941 | | | | | | | | | | |
| STRUCTURE | .1941(A)(2) | | | | | | | | | | |
| MINERALOGY | .1941(A)(3) | | | | | | | | | | |
| SOIL WETNESS | .1942 | 0" | 6" | 24" | 16" | 16" | 0" | | | | |
| RESTRICTIVE HORIZON | .1944 | | | | | | | | | | |
| SAPROLITE | .1943/.1956 | | | | | | | | | | |
| CLASSIFICATION | .1948 | US | US | PS | US | US | US | | | | |
| LONG TERM ACCEPTANCE RANGE | .1955 | | | .3 | | | | | | | |