


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-22	0-24	0-30							
TEXTURE GROUP	.1941(A)(1)	CL	SL	SL							
CONSISTENCE	.1941	VK	VK	VK							
STRUCTURE	.1941(A)(2)	G	G	G							
MINERALOGY	.1941(A)(3)	NCP	NCP	NCP							
HORIZON 2 DEPTH		22-36	24-46								
TEXTURE GROUP	.1941(A)(1)	SC	SC								
CONSISTENCE	.1941	F	F								
STRUCTURE	.1941(A)(2)	SBL	SBL								
MINERALOGY	.1941(A)(3)	NCP	NCP								
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942			30"							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	P5	P5	P5							
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4	.5							

ⓐ



ⓑ

ⓒ

