

Harnett County
Department of Public Health
307 Cornelius Harnett Boulevard
Lillington, North Carolina 27546
910-893-7547

**WRITTEN REPORT AND NOTIFICATION OF AN
IMPROVEMENT PERMIT DENIAL**

1. Name of Applicant: *Douglas Behmer* Phone: *910-891-5171*

Address: *345 Gardner Road, Four Oaks, North Carolina 27524*

2. Name of Property Owner: *Gustabo & Wendy Guzman* Phone: *910-897-6193*

Address: *2964 Ashe Avenue, Dunn, North Carolina 28334*

3. Location of denied lot/site/tract (Specific directions) *corner of Ashe Avenue & Red Hill Church Road*

4. Property Size: acres *381.3 x 60*' Area sq. ft.

5. On *December 3, 2001*, the above referenced lot was evaluated by an Environmental Health Specialist from the Harnett County Health Department. The purpose of this evaluation was to determine the suitability of the site to accept subsurface sewage disposal. The site evaluation included the following unsuitable characteristics:

 Unsuitable topography and landscape position (.1940)
 Unsuitable soil characteristics – texture, structure, mineralogy (.1941)
 Soil wetness condition (.1942)
 Inadequate soil depth (.1943)
 Restrictive horizons (.1944)
 Inadequate space (.1945)
 Other

6. Suggested Modifications or Alternatives (if available):

7. The State Sewage Disposal Rules do provide an additional option to you for consideration. Section .1948 (D) states that a site may be used for a ground absorption sewage treatment and disposal system if written documentation including engineering, hydrogeologic, geologic, or soil studies, indicate that a proposed system can reasonably be expected to function satisfactorily.

James E. Manhart 12-4-07
James E. Manhart, R.S. Date

JEM/sgw

WRITTEN REPORT AND NOTIFICATION OF AN IMPROVEMENTS
PERMIT DENIAL

1. Name of Applicant: DOUGLASA Behmer Phone: 891-5171
Address: 345 Gardner Rd Four Oaks N.C. 27524
2. Name of Property Owner: Gustalo + Wendy (Guzman) Phone: 910-887-6193
Address: 2964 Ashe Ave DUNN N.C. 28334
3. Location of denied lot/site/tract (Specific directions)
Corner of Ashe Ave + Red Hill Church Road
4. Property Size: _____ acres Area: 381.3' X 60' sq.ft.
5. On 12-3-01, the above referenced lot was evaluated by an Environmental Health Specialist from the Harnett County Health Department. The purpose of this evaluation was to determine the suitability of the site to accept subsurface sewage disposal. The site evaluation included the following unsuitable characteristics:
 - Unsuitable topography and landscape position (.1940)
 - Unsuitable soil characteristics - texture, structure, mineralogy (.1941)
 - Soil wetness condition (.1942)
 - Inadequate soil depth (.1943)
 - Restrictive horizons (.1944)
 - Inadequate space (.1945)
 - Other
6. Suggested Modifications or Alternatives (if available): _____
7. The State Sewage Disposal Rules do provide an additional option to you for consideration. Section .1948(D) states that a site may be used for a ground absorption sewage treatment and disposal system if written documentation including engineering, hydrogeologic, geologic, or soil studies, indicate that a proposed system can reasonably be expected to function satisfactorily.