

# SITE/SUB-EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		9-10												
Texture Group	.1941(A)(1)	SC												
Consistence	.1941	VK												
Structure	.1941(A)(2)	C												
Mineralogy	.1941(A)(3)	N <sup>6</sup>												
HORIZON 2 DEPTH		18-20												
Texture Group	.1941(A)(1)	SC1												
Consistence	.1941	K												
Structure	.1941(A)(2)	SK												
Mineralogy	.1941(A)(3)	CU												
HORIZON 3 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
HORIZON 4 DEPTH														
Texture Group	.1941(A)(1)													
Consistence	.1941													
Structure	.1941(A)(2)													
Mineralogy	.1941(A)(3)													
SOIL WETNESS	.1942	73"												
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/.1956													
CLASSIFICATION	.1948	PS												
LONG TERM ACCEPTANCE RATE	.1955	.9												

  
 18-22  
 4x75" R1