

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-12	0-14	0-10							
TEXTURE GROUP	.1941(A)(1)	SL	SL	SL							
CONSISTENCE	.1941	VH	VH	VH							
STRUCTURE	.1941(A)(2)	C	C	C							
MINERALOGY	.1941(A)(3)	NBY	NBY	NBY							
HORIZON 2 DEPTH		12-34	14-30	10-30							
TEXTURE GROUP	.1941(A)(1)	SCl	SCl	SCl							
CONSISTENCE	.1941	V	V	V							
STRUCTURE	.1941(A)(2)	SBK	SBK	SBK							
MINERALOGY	.1941(A)(3)	SCB	SCB	SCB							
HORIZON 3 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	34"	25"								
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	P5	US(P5)	P5							
LONG TERM ACCEPTANCE RANGE	.1955	4	.5	.4							

Point



Rac