



SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES													
		1	2	3	4	5	6	7	8	9	10				
LANDSCAPE POSITION	.1940														
SLOPE (%)	.1940														
HORIZON 1 DEPTH		0-6	0-6												
TEXTURE GROUP	.1941(A)(1)	SL	SL												
CONSISTENCE	.1941	VFr	VFr												
STRUCTURE	.1941(A)(2)	C	C												
MINERALOGY	.1941(A)(3)	WHA	MHP												
HORIZON 2 DEPTH		6-36	6-32												
TEXTURE GROUP	.1941(A)(1)	C	C												
CONSISTENCE	.1941	Fr	Fr												
STRUCTURE	.1941(A)(2)	SL	SL												
MINERALOGY	.1941(A)(3)	SCD	SCD												
HORIZON 3 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
HORIZON 4 DEPTH															
TEXTURE GROUP	.1941(A)(1)														
CONSISTENCE	.1941														
STRUCTURE	.1941(A)(2)														
MINERALOGY	.1941(A)(3)														
SOIL WETNESS	.1942														
RESTRICTIVE HORIZON	.1944														
SAPROLITE	.1943/.1956														
CLASSIFICATION	.1948	05	15												
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4												



Big "J" Street

4x75 18.24
if full foot to
line could be
pump will be engaged



PRICELAND ESTATES