

SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	6									
SLOPE (%)	.1940	2									
HORIZON 1 DEPTH		0-10									
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FR									
STRUCTURE	.1941(A)(2)	OK									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 2 DEPTH		10-14									
TEXTURE GROUP	.1941(A)(1)	SL									
CONSISTENCE	.1941	FR									
STRUCTURE	.1941(A)(2)	OK									
MINERALOGY	.1941(A)(3)	NSNP									
HORIZON 3 DEPTH		14-36									
TEXTURE GROUP	.1941(A)(1)	SL-CL									
CONSISTENCE	.1941	SL FRM									
STRUCTURE	.1941(A)(2)	STBN									
MINERALOGY	.1941(A)(3)	SSNP									
HORIZON 4 DEPTH											
TEXTURE GROUP	.1941(A)(1)										
CONSISTENCE	.1941										
STRUCTURE	.1941(A)(2)										
MINERALOGY	.1941(A)(3)										
SOIL WETNESS	.1942	28	28	26							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RANGE	.1955	.3	.35	.3							

Tank System.

RIVERLAND ESTATES

LOT #2

12' Soil and Gravel Path

S55°07'46"W
219.61'

163.03'

1
0.71 acres

212.45'

N24°51'21"W
125.00'

125.00'

1/2

S65°08'39"W

2

0.61 acres

76'

24'

70'

40'

S65°08'39"W

Sold

0.61

125'

125.00'

S25°

124.90'

S26°36'24"E
WTR

S25°21'34"E
WTR

OLD STAGE ROAD SOUTH

SR 1769

SR