

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940	L												
SLOPE (%)	.1940	Z												
HORIZON 1 DEPTH		0-12			0-8	0-8	0-8							
TEXTURE GROUP	.1941(A)(1)	SL												
CONSISTENCE	.1941	FC												
STRUCTURE	.1941(A)(2)	GR												
MINERALOGY	.1941(A)(3)	NSMP												
HORIZON 2 DEPTH		12-18												
TEXTURE GROUP	.1941(A)(1)	SCL	11	11										
CONSISTENCE	.1941	FC												
STRUCTURE	.1941(A)(2)	GM-SB2												
MINERALOGY	.1941(A)(3)	SSSP												
HORIZON 3 DEPTH		18-42												
TEXTURE GROUP	.1941(A)(1)	SC-CL												
CONSISTENCE	.1941	SL-Fat												
STRUCTURE	.1941(A)(2)	S <sub>2</sub> te												
MINERALOGY	.1941(A)(3)	S.P												
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942	36	39	36	28	24	24							
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943/1956													
CLASSIFICATION	.1948													
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4	.4	.3	.25	.25							