

HTE 04-5-104812

OPERATIONS PERMIT

Name: (owner) KATHERINE STANTON
Property Location: SR# 1727 SUGGS
Subdivision WALTS CROSSING
Tax ID # _____
Contractor: T+S DENNING RAINES

New Installation Septic Tank
 Repairs Nitrification Line
Lot # 9
Quadrant # _____
Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 50' ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other 25% Reduction

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 1 exact length of each ditch 360 ft. width of ditches 3 ft. depth of ditches 12 in.

French Drain Required: - Linear feet

Date: 11-12-04

Inspected by: James E. Markham
Environmental Health Specialist

PERMIT NO. 21372

