Authorized State Agent

| PERMIT # <u>24217</u> | Operation Permit | |
|---|--|--|
| | | □ Repair □ Nitrification Line □ Expansion |
| Name: (owner) DONNIR LEE | CHEDINICION | LOT # |
| System Installer: Rocky Road Suche Tablo Basement with plumbing: Garage Number of Bedr Type of Water Supply: Community Public System Type: 25% Reduction System Type Table (In accordance with Table V a) This system has been installed in compliance with applicable Morth Carolina Gen | Registration # | expire in 5 years. nths prior to expiration for permit renewal. |
| ins system has been instance in compilance with appreciable north caronna den | 9 L' | unions of the improvement Perint and Construction Audionzation. |
| 25 | 25% RED REPATIL. 15' Decu 50' SFD 54' A | |
| | T 100' 50' AWAY | |
| 1.20 | SRIBOS LEERD | |
| PERMIT CONDITIONS: System shall perform in accordance with lil. Monitoring: As required by Rule .1961. Maintenance: As required by Rule .1961. Other: Subsurface system operator required? Yes | | |
| If yes, see attached sheet for additional IV. Operation: | operation conditions, maintenance and reporting. | |
| V. Other: | | |
| Subsurface No. of exact | | JOGO gallons Pump Tank: gallons depth of feet ditchesZZ→18 inches |

Date _