HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: <u>Scott Forman</u> Phone #: <u>309-1175</u>

Address: 289 Buckhorn Rd Spring Lake NC28390

Name of Mobile Home Park or S/D: _____

Name of Owner (if different):

Address of Owner (if different):

Property Location (State Road name and #): Ray Rd

Purpose of Inspection: Metal Farm Building (30'x50')

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

- 1. the intended use of the septic system should change, and/or
- 2. the system should fail or malfunction, and/or
- 3. the owner or tenant of the property change, and/or
- 4. after six months

BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM

non

AUTHORIZATION OF EXISTING SYSTEM

Signature of Environmental Health Specialist