





# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940				H <sub>2</sub> O IN PIT						
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-33	0-24	0-17	0-21	0-20"	0-14	0-42"	0-16"		0-43"
Texture Group	.1941(A)(1)	SL	SL	SL	SL	SL	SL	C	SL		SL
Consistence	.1941	VFR	VFR	VFR		VFR	VFR	FI	VFR		VFR
Structure	.1941(A)(2)	G	G	G		G	G	SBK/M	G		G
Mineralogy	.1941(A)(3)	NS/NP	NS/NP	NS/NP		NS/NP	NS/NP	S/P	NS/NP		NS/NP
HORIZON 2 DEPTH		33-48"	24-31	17-29	21"-37"	20"±	14-19		16"±		43"±
Texture Group	.1941(A)(1)	C	SCL	SCL	SCL		SC/SL		C		SC
Consistence	.1941	FR	FR	FR	F		FR/RI		FI		F
Structure	.1941(A)(2)	SBK	SBK	SBK	SBK		SBK		M		SBK
Mineralogy	.1941(A)(3)	S/P	S/P	S/SC	S/P		S/P				SS/SP
HORIZON 3 DEPTH			31"	29"±	37"±		19"				
Texture Group	.1941(A)(1)		C	C	C		C				
Consistence	.1941		VF	FI	FI		FI				
Structure	.1941(A)(2)		ABK	ABK	ABK		SBK				
Mineralogy	.1941(A)(3)		VS/VP	VS/VP	VS/VP		S/P				
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	44"	33"	21"		20	23"	4"	20"		
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	PS	PS	US	PS	US	US	US	US		PS
LONG TERM ACCEPTANCE RATE	.1955	.3	.3		.3						.8

