

# SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-32	0-28	0-32	0-27	0-26	0-38	0-21	0-31	0-22	0-17
Texture Group	.1941(A)(1)	SL	SL	SL	SL	SL	SL	SL	SL	SL	SL
Consistence	.1941	Vfr	Vfr	Vfr	Vfr	Vfr	Vfr	Vfr	Vfr	Vfr	Vfr
Structure	.1941(A)(2)	C	C	C	C	C	C	C	C	C	C
Mineralogy	.1941(A)(3)	NS/MP	NS/MP	NS/MP	NS/MP	NS/MP	NS/MP	NS/MP	NS/MP	NS/MP	NS/MP
HORIZON 2 DEPTH		32-42	28-40	32-48	27-41	20-41	38-48	21-40	31-48	22-34	17-40
Texture Group	.1941(A)(1)	SCl	SCl	SCl	SCl	SCl	SCl	SCl	SCl	SCl	SCl
Consistence	.1941	F	F	F	F	F	F	F	F	F	F
Structure	.1941(A)(2)	Sbk	Sbk	Sbk	Sbk	Sbk	Sbk	Sbk	Sbk	Sbk	Sbk
Mineralogy	.1941(A)(3)	S/SP	S/SP	S/SP	S/SP	S/SP	S/SP	S/SP	S/SP	S/SP	S/SP
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	44"	40"		41"	41"		38"			37"
RESTRICTIVE HORIZON	.1944									34" PM	
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	PS	PS	PS	PS	PS	PS	PS	PS	PS	PS
LONG TERM ACCEPTANCE RATE	.1955	.45	.45	.45	.45	.45	.45	.45	.45	.45	.45



