HTE # 04-5-101002

## RNETT COUNTY HEALTH DEP MENT ENVIRONMENTAL HEALTH SECTION

17756

## **OPERATIONS PERMIT**

Name: (owner)	LLINGS CO	N57. NC	New I	nstallation Sept	ic Tank  Repair
Property Location: SI Subdivision Nesse					
Contractor:	ON MARTHE	ins		Registration #	
Basement with Plumb	ing: 🗆	Garage: 🗵			
Water Supply:  Well Public Community  Distance From Well:   100 ft.					
Following are the specifications for the sewage disposal system on above captioned property.					
Type of system:	Conventional	Other Pump To	Poris	TIRENE AGGRECAT	ERENCH
Size of tank: Septic Tank: 1000 gallons Pump Tank: 1000 gallons					
Subsurface Drainage Field	No. of ditches	exact length of each ditch 3°	o_ft.	width of ditches 3 ft.	depth of ditches 12 in.
French Drain Require	d:	Linear feet	Date:	8 18 05	
PERMIT NO. 2169	13		Inspec	eted by:	25/1/1/1/1/

