

HTE # 04-5-10384

# OPERATIONS PERMIT

Name: (owner) Johnny Bensley  New Installation  Septic Tank  Repair

Property Location: SR# 1416 SPENCE MILL RD  Nitrification Line  Expansion  
Subdivision Harvey C Bensley Lot # 4 Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_

Contractor: Bryant Grading Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community  
Distance From Well: 50' ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other \_\_\_\_\_

Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field No. of ditches 2 exact length of each ditch 100 ft. width of ditches 3 ft. depth of ditches 24-30 in.

French Drain Required: - Linear feet Date: 4-29-05

PERMIT NO. 21353 Inspected by: James E. Markant

