

HTE # 04-5-10712

HAMILTON COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION

18672

OPERATIONS PERMIT

Name: (owner) ROBERT & LISA GUY New Installation Septic Tank Repair

Property Location: SR# 2016 ROSS RD Nitrification Line Expansion
Subdivision _____ Lot # _____ Tax ID # _____ Quadrant # _____

Contractor: GERALD TEMPLE Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community
Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 3 exact length of each ditch 100 ft. width of ditches 3 ft. depth of ditches 18 in.

French Drain Required: _____ Linear feet Date: 6/22/06

PERMIT NO. 21419 Inspected by: [Signature] RS

13.93 ac
LOT

