

APPLICANT NAME \_\_\_\_\_

DATE \_\_\_\_\_

FACTORS		PROCESSES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		C-8	O-12							
Texture Group	.1941(A)(1)	LS	LS							
Consistence	.1941	VF	VB							
Structure	.1941(A)(2)	C	C							
Mineralogy	.1941(A)(3)	NOA	NOA							
HORIZON 2 DEPTH		8-36	12-76							
Texture Group	.1941(A)(1)	SC1	SC1							
Consistence	.1941	F	F							
Structure	.1941(A)(2)	SP	SP							
Mineralogy	.1941(A)(3)	NOA	NOA							
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942									
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	PS	PS							
LONG TERM ACCEPTANCE RATE	.1955	.3	.3							

Handwritten marks: a circled 'C', a circled 'O', and a bracket-like shape.