HTE # 05-5-13048 Bara-13049

RNETT COUNTY HEALTH DEPA MENT ENVIRONMENTAL HEALTH SECTION

18382

OPERATIONS PERMIT

Name: (owner) DONAID + KAREN STEPHENSON	New Installation Septic Tank Repair
Property Location: SR# 1412 Clienter Light Subdivision Lot # Tax ID #	Nitrification Line
Contractor: Adeale brownter	Registration #
Basement with Plumbing: Garage:	
Water Supply: Well Public Community Distance From Well: ft.	
Following are the specifications for the sewage dispos	al system on above captioned property.
Type of system: Conventional Other 25% is	reduction System
Size of tank: Septic Tank: gallons Pum	np Tank: gallons
Subsurface No. of exact length of each ditch //	width of depth of ditches 3 ft. ditches 24 in.
French Drain Required: Linear feet	Inspected by pames Mulantana
PERMIT NO. 22770	Inspected by Ames CMalant and Pill