

HTE # 06-5-13727R

HAMILTON COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH SECTION

18459

OPERATIONS PERMIT

Name: (owner) Bill Clark Homes New Installation Septic Tank Repair

Property Location: SR# 1139 Nitrification Line Expansion

Subdivision Pattons Point Lot # 115 Tax ID # _____ Quadrant # _____

Contractor: Jones Septic Registration # _____

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other Quick 4 Chamber

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface Drainage Field No. of ditches 1 exact length of each ditch 150 ft. width of ditches 3 ft. depth of ditches 18-24 in.

French Drain Required: _____ Linear feet

Date: 12/6/2006

PERMIT NO. 22533

Inspected by: Ryan McLean, R.L.

