

HTE # 06-5-14214

# OPERATIONS PERMIT

Name: (owner) J+S DEVELOPMENT  New Installation  Septic Tank  Repair

Property Location: SR# 1125 LEMUEL BLACK RD  Nitrification Line  Expansion  
Subdivision CARLITE Hills Fms Lot # 43 Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_

Contractor: OTIS STRICKLAND Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community

Distance From Well: 100 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other POLYSTYRENE AGGREGATE TRENCH

Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field No. of exact length width of depth of  
ditches 3 of each ditch 100 ft. ditches 3 ft. ditches 24-38 in.

French Drain Required: \_\_\_\_\_ Linear feet

Date: 8/9/06

PERMIT NO. 2222

Inspected by: [Signature]

