HTE # 06-5-15258

## RNETT COUNTY HEALTH DEP TMENT ENVIRONMENTAL HEALTH SECTION

18713

## **OPERATIONS PERMIT**

Name: (owner) TCH Compacting & Dev Grove New Installation Septic Tank   Repair
Property Location: SR# 2026 Byro Powo Ro
Contractor: Johes Septic TANK SEPTICE Registration #
Basement with Plumbing:  Garage:
Water Supply:  Well Public Community  Distance From Well:   too ft.
Following are the specifications for the sewage disposal system on above captioned property.
Type of system:   Conventional Other Ouck 4 CHAMBER
Size of tank: Septic Tank: 1000 gallons Pump Tank: gallons
Subsurface No. of exact length width of depth of Drainage Field ditches 3 of each ditch 75 ft. ditches 3 ft. ditches 3 in.
French Drain Required: Linear feet Date: Date: 9 12 06
PERMIT NO. 21 795 Inspected by: Wes
CREEK DR 1 3 BERROOM L HO' DR 173'

BRANTON CT