
ADDRESS . : 90 WOOD POINT DR SUBDIV: WOODSHIRE
CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
OWNER . . : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
PARCEL . . : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561

_____ *AP-MR*

----- COMMENTS AND NOTES -----

ADDRESS . . : 90 WOOD POINT DR
CONTRACTOR : H & H CONSTRUCTORS INC
OWNER . . . : H & H CONSTRUCTOR INC #146
PARCEL . . . : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00
PROPOSED USE : SFD
SEWER : UNKNOWN
BASEMENT : NA
SEPTIC - EXISTING? : NEW
WATER SUPPLY : UNKNOWN

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940

 AP 11/20/06

----- COMMENTS AND NOTES -----

ADDRESS . : 90 WOOD POINT DR SUBDIV: WOODSHIRE
CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
OWNER . . : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
PARCEL . . : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940
	11/20/06	AP	
A814 01	11/27/06	TI	ADDRESS CONFIRMATION VRU #: 001310968
	11/20/06	AP	90 WOOD POINT DR LOT 146
P309 01	11/29/06	TI	R*PLUMB UNDER SLAB VRU #: 001314866

 AP-mr

----- COMMENTS AND NOTES -----

ADDRESS . . : 90 WOOD POINT DR SUBDIV: WOODSHIRE
CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
OWNER . . . : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
PARCEL . . . : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940
	11/20/06	AP	
A814 01	11/27/06	TI	ADDRESS CONFIRMATION VRU #: 001310968
	11/20/06	AP	90 WOOD POINT DR LOT 146
P309 01	11/29/06	MR	R*PLUMB UNDER SLAB VRU #: 001314866
	11/29/06	AP	
B111 01	11/30/06	TI	R*BLDG SLAB INSP VRU #: 001315678
	11/30/06	CA	
B111 02	12/01/06	TI	R*BLDG SLAB INSP VRU #: 001316355

Garrett

----- COMMENTS AND NOTES -----

ADDRESS . . : 90 WOOD POINT DR SUBDIV: WOODSHIRE
CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
OWNER . . . : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
PARCEL . . . : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940
	11/20/06	AP	
A814 01	11/27/06	TI	ADDRESS CONFIRMATION VRU #: 001310968
	11/20/06	AP	90 WOOD POINT DR LOT 146
P309 01	11/29/06	MR	R*PLUMB UNDER SLAB VRU #: 001314866
	11/29/06	AP	
B111 01	11/30/06	TI	R*BLDG SLAB INSP VRU #: 001315678
	11/30/06	CA	
B111 02	12/01/06	TI	R*BLDG SLAB INSP VRU #: 001316355
	12/01/06	CA	
B111 03	12/04/06	TI	R*BLDG SLAB INSP VRU #: 001317197

AP-IVR

----- COMMENTS AND NOTES -----

ADDRESS . : 90 WOOD POINT DR SUBDIV: WOODSHIRE
CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
OWNER . . : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
PARCEL . . : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940
	11/20/06	AP	
A814 01	11/27/06	TI	ADDRESS CONFIRMATION VRU #: 001310968
	11/20/06	AP	90 WOOD POINT DR LOT 146
P309 01	11/29/06	MR	R*PLUMB UNDER SLAB VRU #: 001314866
	11/29/06	AP	
B111 01	11/30/06	TI	R*BLDG SLAB INSP VRU #: 001315678
	11/30/06	CA	
B111 02	12/01/06	TI	R*BLDG SLAB INSP VRU #: 001316355
	12/01/06	CA	
B111 03	12/04/06	MR	R*BLDG SLAB INSP VRU #: 001317197
	12/04/06	AP	
R425 01	1/11/07	TI	FOUR TRADE ROUGH IN VRU #: 001335610

DA-MR

----- COMMENTS AND NOTES -----

DO NOT REMOVE!

Harnett County Inspection Department

102 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7527 • Fax: (910) 893-2793

Job Name: H+H Date: 1-11-7

Address: 90 Woodpoint

Lot No.: 146 Permit No.: _____

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|-------------------------------------|----------------------------------|--|-------------------------------------|---------------------------------------|---------------------------------|--------------------------------------|
| <input type="checkbox"/> Footing | <input type="checkbox"/> Foundation | <input type="checkbox"/> Bldg. | <input type="checkbox"/> Elec. | <input type="checkbox"/> Plumb. | <input type="checkbox"/> Mech. | <input type="checkbox"/> Insul. | <input type="checkbox"/> Floor Fram. |
| <input type="checkbox"/> Floor Slab | <input type="checkbox"/> MFG. Home | <input type="checkbox"/> Modular | <input type="checkbox"/> Damp/Water Proof. | <input type="checkbox"/> Structural | <input type="checkbox"/> Wall Sheath. | <input type="checkbox"/> Other | |

Violations Found: _____

- 1) Fireblock or caulk all Plumbing Pipes through Plates at hall closet
 - 2) No Fire place
 - 3) Tempered window by back door
 - 5) Fireblock behind Dryer
 - 6) Support Short beams holding rafters at ~~the~~ Room upstairs
 - 7) No DWV or plumb. pressure tests
- No Tie-down bolts on Middle wall under A O-2 Trusses and NO footer?

Code Enforcement Official
Signature Mik Ream

Date: _____

It is unlawful for any sub contractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation.

ADDRESS : 90 WOOD POINT DR SUBDIV: WOODSHIRE
CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
OWNER : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
PARCEL : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940
	11/20/06	AP	
A814 01	11/27/06	TI	ADDRESS CONFIRMATION VRU #: 001310968
	11/20/06	AP	90 WOOD POINT DR LOT 146
P309 01	11/29/06	MR	R*PLUMB UNDER SLAB VRU #: 001314866
	11/29/06	AP	
B111 01	11/30/06	TI	R*BLDG SLAB INSP VRU #: 001315678
	11/30/06	CA	
B111 02	12/01/06	TI	R*BLDG SLAB INSP VRU #: 001316355
	12/01/06	CA	
B111 03	12/04/06	MR	R*BLDG SLAB INSP VRU #: 001317197
	12/04/06	AP	
R425 01	1/11/07	MR	FOUR TRADE ROUGH IN VRU #: 001335610
	1/11/07	DA	<ul style="list-style-type: none"> ✓ fireblock at plumbing in hall closet ✓ no fireplace X need tempered window at back door ✓ fireblock chase behind dryer ✓ support short beams holding rafters at second fl. bedroom X no DWV or pressure tests ready ✓ ✓ no tie down bolts at bearing wall in living room
R425 02	1/17/07	TI	FOUR TRADE ROUGH IN VRU #: 001338537
	1/17-07	DA-CE	

COMMENTS AND NOTES

DO NOT REMOVE!

Harnett County Inspection Department

102 East Front Street • P.O. Box 65

Lillington, NC 27546

Phone: (910) 893-7527 • Fax: (910) 893-2793

Job Name: NH H Date: 1-17-07

Address: 90 Wood pt.

Lot No.: 146 Permit No.: 06-50015615

(Check Box for Violation)

- | | | | | | | | |
|-------------------------------------|-------------------------------------|----------------------------------|--|-------------------------------------|---------------------------------------|---------------------------------|--------------------------------------|
| <input type="checkbox"/> Footing | <input type="checkbox"/> Foundation | <input type="checkbox"/> Bldg. | <input type="checkbox"/> Elec. | <input type="checkbox"/> Plumb. | <input type="checkbox"/> Mech. | <input type="checkbox"/> Insul. | <input type="checkbox"/> Floor Fram. |
| <input type="checkbox"/> Floor Slab | <input type="checkbox"/> MFG. Home | <input type="checkbox"/> Modular | <input type="checkbox"/> Damp/Water Proof. | <input type="checkbox"/> Structural | <input type="checkbox"/> Wall Sheath. | <input type="checkbox"/> Other | |

Violations Found: The following from previous inspection not done:

- ① No water in drain test
- ② Need tempered glass in window by back door (This can be done by final)

OK for siding & insulation

Code Enforcement Official
Signature C. Edgerth

Date: 1-17-07

It is unlawful for any sub contractor, general contractor, or owner to cover or cause to be covered any part of the work with flooring, sheetrock, earth or other material until the proper inspector had ample time to approve the installation.

ADDRESS : 90 WOOD POINT DR SUBDIV: WOODSHIRE
CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
OWNER : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
PARCEL : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940
	11/20/06	AP	
A814 01	11/27/06	TI	ADDRESS CONFIRMATION VRU #: 001310968
	11/20/06	AP	90 WOOD POINT DR LOT 146
P309 01	11/29/06	MR	R*PLUMB UNDER SLAB VRU #: 001314866
	11/29/06	AP	
B111 01	11/30/06	TI	R*BLDG SLAB INSP VRU #: 001315678
	11/30/06	CA	
B111 02	12/01/06	TI	R*BLDG SLAB INSP VRU #: 001316355
	12/01/06	CA	
B111 03	12/04/06	MR	R*BLDG SLAB INSP VRU #: 001317197
	12/04/06	AP	
R425 01	1/11/07	MR	FOUR TRADE ROUGH IN VRU #: 001335610
	1/11/07	DA	fireblock at plumbing in hall closet no fireplace need tempered window at back door fireblock chase behind dryer support short beams holding rafters at second fl. bedroom no DWV or pressure tests ready no tie down bolts at bearing wall in living room
R425 02	1/17/07	CE	FOUR TRADE ROUGH IN VRU #: 001338537
	1/17/07	DA	THE FOLLOWING FROM PREVIOUS INSPECTION NOT DONE: 1) NO WATER IN DRAIN TEST 2) NEED TEMPERED GLASS BY REAR DOOR (CAN DO THIS BY FINAL) OK FOR SIDING AND INSULATION. CE
R425 03	1/22/07	TI	FOUR TRADE ROUGH IN VRU #: 001341113
	<u>1-22-07</u>	<u>D/A</u>	

COMMENTS AND NOTES

*no drain test
OK to insulate*

ADDRESS : 90 WOOD POINT DR SUBDIV: WOODSHIRE
CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
OWNER : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
PARCEL : 01-0536-04- -0028- -45-
APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
146 JB

STRUCTURE: 000 000 42X68 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940
	11/20/06	AP	
A814 01	11/27/06	TI	ADDRESS CONFIRMATION VRU #: 001310968
	11/20/06	AP	90 WOOD POINT DR LOT 146
P309 01	11/29/06	MR	R*PLUMB UNDER SLAB VRU #: 001314866
	11/29/06	AP	
B111 01	11/30/06	TI	R*BLDG SLAB INSP VRU #: 001315678
	11/30/06	CA	
B111 02	12/01/06	TI	R*BLDG SLAB INSP VRU #: 001316355
	12/01/06	CA	
B111 03	12/04/06	MR	R*BLDG SLAB INSP VRU #: 001317197
	12/04/06	AP	
R425 01	1/11/07	MR	FOUR TRADE ROUGH IN VRU #: 001335610
	1/11/07	DA	fireblock at plumbing in hall closet no fireplace need tempered window at back door fireblock chase behind dryer support short beams holding rafters at second fl. bedroom no DWV or pressure tests ready no tie down bolts at bearing wall in living room
R425 02	1/17/07	CE	FOUR TRADE ROUGH IN VRU #: 001338537
	1/17/07	DA	THE FOLLOWING FROM PREVIOUS INSPECTION NOT DONE: 1) NO WATER IN DRAIN TEST 2) NEED TEMPERED GLASS BY REAR DOOR (CAN DO THIS BY FINAL) OK FOR SIDING AND INSULATION. CE
R425 03	1/22/07	CE	FOUR TRADE ROUGH IN VRU #: 001341113
	1/22/07	DA	still no water in drain test. will check this on insulation inspection. ce ok to insulate. ce
I129 01	1/24/07	TI	R*INSULATION INSPECTION VRU #: 001342005
		AP-IVR	
R425 04	1/24/07	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001342880
		AP-IVR	

COMMENTS AND NOTES

ADDRESS : 90 WOOD POINT DR SUBDIV: WOODSHIRE
 CONTRACTOR : H & H CONSTRUCTORS INC PHONE :
 OWNER : H & H CONSTRUCTOR INC #146 PHONE : (910) 486-4864
 PARCEL : 01-0536-04- -0028- -45-
 APPL NUMBER: 06-50015615 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : HWY 27 TO NURSERY RD TURN LEFT ON
 NURSERY RD LEFT ON LEMUEL BLACK RD LEFT
 ON WOODSHIRE DR INTO WOODSHIRE S/D LOT
 146 JB

STRUCTURE: 000 000 42X68 4BDR
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/06	MR	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001307561
	11/14/06	AP	
B103 01	11/20/06	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001310940
	11/20/06	AP	
A814 01	11/27/06	TI	ADDRESS CONFIRMATION VRU #: 001310968
	11/20/06	AP	✓ 90 WOOD POINT DR LOT 146
P309 01	11/29/06	MR	R*PLUMB UNDER SLAB VRU #: 001314866
	11/29/06	AP	
B111 01	11/30/06	TI	R*BLDG SLAB INSP VRU #: 001315678
	11/30/06	CA	
B111 02	12/01/06	TI	R*BLDG SLAB INSP VRU #: 001316355
	12/01/06	CA	
B111 03	12/04/06	MR	R*BLDG SLAB INSP VRU #: 001317197
	12/04/06	AP	
R425 01	1/11/07	MR	FOUR TRADE ROUGH IN VRU #: 001335610
	1/11/07	DA	fireblock at plumbing in hall closet no fireplace need tempered window at back door fireblock chase behind dryer support short beams holding rafters at second fl. bedroom no DWV or pressure tests ready no tie down bolts at bearing wall in living room
R425 02	1/17/07	CE	FOUR TRADE ROUGH IN VRU #: 001338537
	1/17/07	DA	THE FOLLOWING FROM PREVIOUS INSPECTION NOT DONE: 1) NO WATER IN DRAIN TEST 2) NEED TEMPERED GLASS BY REAR DOOR (CAN DO THIS BY FINAL) OK FOR SIDING AND INSULATION. CE
R425 03	1/22/07	CE	FOUR TRADE ROUGH IN VRU #: 001341113
	1/22/07	DA	still no water in drain test. will check this on insulation inspection. ce ok to insulate. ce
I129 01	1/24/07	MR	R*INSULATION INSPECTION VRU #: 001342005
	1/24/07	AP	
R425 04	1/24/07	MR	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001342880
	1/24/07	AP	
H824 01	2/26/07	JW	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001362300
	2/26/07	AP	
R429 01	3/26/07	TI	FOUR TRADE FINAL VRU #: 001376870

3-26-07 AP-CE

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Res. SFD
Type of Construction: —
Owner of Building: H & H Constr.
Building Address: 90 Wood Pt.
Zoning District: —
Zoning Permit No.: —

Conditional Use Permit No.: —
Building Permit No.: 06-50015615
Electrical Permit No.: "
Insulation Permit No.: "
Plumbing Permit No.: "
Mech. Permit No.: "
Envir. C.O. No.: —

Date: 3-26-07

C. Edwards
Building Official

Zoning Official