HTE #06-5-15682

## HA ETT COUNTY HEALTH DEPAR...ENT ENVIRONMENTAL HEALTH SECTION

18468

## **OPERATIONS PERMIT**

OI LIMITONO I LIMITI
Name: (owner) Davidson Home Croffes New Installation Septic Tank   Repair
Property Location: SR# 401
Contractor: Clen Caroll Registration #
Basement with Plumbing:  Garage:
Water Supply:   Well Public Community  Distance From Well: ft.
Following are the specifications for the sewage disposal system on above captioned property.
Type of system:   Conventional Other EZF/ow
Size of tank: Septic Tank: gallons Pump Tank: gallons
Subsurface No. of exact length width of depth of Drainage Field ditches 3 of each ditch 80 ft. ditches 3 ft. ditches 1 ft.
French Drain Required: Linear feet Date: Date:
PERMIT NO. 23145 Inspected by: Duya Medican, R.S.
De Ross  Hoss  Conv.  Reconstruction  Reconstr

50 Private Rd.