
ADDRESS . : 131 BRENDAMOORE CT
CONTRACTOR : BULLOCK BUILDERS INC KEITH
OWNER . . : ATKINS PLACE LLC #6
PARCEL . . : 08-0653- - -0030- -23-
APPL NUMBER: 06-50015746 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 6. 401N FROM
LILLINGTON LEFT ON CHALYBEATE RD LEFT
ON DEXTERFIELD DR LOT ON LEFT.
-A.DRIGGERS

SUBDIV: DEXTERFIELD
PHONE : (919) 639-7424
PHONE :

STRUCTURE: 000 000 60X60 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/04/06 <i>10-4-06</i>	TI <i>APBS</i>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001285188

COMMENTS AND NOTES -----

ADDRESS . : 131 BRENDAMOORE CT SUBDIV: DEXTERFIELD
CONTRACTOR : BULLOCK BUILDERS INC KEITH PHONE : (919) 639-7424
OWNER . . : ATKINS PLACE LLC #6 PHONE :
PARCEL . . : 08-0653- - -0030- -23-
APPL NUMBER: 06-50015746 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 6. 401N FROM
LILLINGTON LEFT ON CHALYBEATE RD LEFT
ON DEXTERFIELD DR LOT ON LEFT.
-A.DRIGGERS

STRUCTURE: 000 000 60X60 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/04/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001285188
	10/04/06	AP	
B103 01	10/16/06	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001291872
	<u>10-16-06</u>	<u>AEB</u>	

----- COMMENTS AND NOTES -----

ADDRESS . : 131 BRENDA MOORE CT SUBDIV: DEXTERFIELD
CONTRACTOR : BULLOCK BUILDERS INC KEITH PHONE : (919) 639-7424
OWNER . . : ATKINS PLACE LLC #6 PHONE :
PARCEL . . : 08-0653- - -0030- -23-
APPL NUMBER: 06-50015746 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 6. 401N FROM
LILLINGTON LEFT ON CHALYBEATE RD LEFT
ON DEXTERFIELD DR LOT ON LEFT.
-A.DRIGGERS

STRUCTURE: 000 000 60X60 3BR SFD
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/04/06 10/04/06	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001285188
B103 01	10/16/06 10/16/06	BS AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001291872 bolt missing on rear wall near right rear corner of house. Have mason install bolt before floor framing
A814 01	10/19/06 10/16/06	TI AP	ADDRESS CONFIRMATION VRU #: 001291881 131 BRENDA MOORE CT LOT 23
B105 01	11/02/06	TI	R*OPEN FLOOR VRU #: 001302389

11-206 APB

----- COMMENTS AND NOTES -----

ADDRESS . . : 131 BRENDAMOORE CT SUBDIV: DEXTERFIELD
CONTRACTOR : BULLOCK BUILDERS INC KEITH PHONE : (919) 639-7424
OWNER . . : ATKINS PLACE LLC #6 PHONE :
PARCEL . . : 08-0653- - -0030- -23-
APPL NUMBER: 06-50015746 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 6. 401N FROM
LILLINGTON LEFT ON CHALYBEATE RD LEFT
ON DEXTERFIELD DR LOT ON LEFT.
-A.DRIGGERS

STRUCTURE: 000 000 60X60 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/04/06 10/04/06	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001285188
B103 01	10/16/06 10/16/06	BS AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001291872 bolt missing on rear wall near right rear corner of house. Have mason install bolt before floor framing
A814 01	10/19/06 10/16/06	TI AP	ADDRESS CONFIRMATION VRU #: 001291881 131 BRENDAMOORE CT LOT 23
B105 01	11/02/06 11/02/06	BS AP	R*OPEN FLOOR VRU #: 001302389
R425 01	11/22/06	TI <u>CA</u>	FOUR TRADE ROUGH IN VRU #: 001312467

----- COMMENTS AND NOTES -----

ADDRESS : 131 BRENDA MOORE CT
CONTRACTOR : BULLOCK BUILDERS INC KEITH
OWNER . . : ATKINS PLACE LLC #6
PARCEL . . : 08-0653- - -0030- -23-
APPL NUMBER: 06-50015746 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 6. 401N FROM
LILLINGTON LEFT ON CHALYBEATE RD LEFT
ON DEXTERFIELD DR LOT ON LEFT.
-A.DRIGGERS

SUBDIV: DEXTERFIELD
PHONE : (919) 639-7424
PHONE :

STRUCTURE: 000 000 60X60 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/04/06 10/04/06	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001285188
B103 01	10/16/06 10/16/06	BS AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001291872 bolt missing on rear wall near right rear corner of house. Have mason install bolt before floor framing
A814 01	10/19/06 10/16/06	TI AP	ADDRESS CONFIRMATION VRU #: 001291881 131 BRENDA MOORE CT LOT 23
B105 01	11/02/06 11/02/06	BS AP	R*OPEN FLOOR VRU #: 001302389
R425 01	11/22/06 11/22/06	TI CA	FOUR TRADE ROUGH IN VRU #: 001312467
R425 02	11/27/06	TI	FOUR TRADE ROUGH IN VRU #: 001313022

11-27-06 DABS

COMMENTS AND NOTES

ADDRESS . : 131 BRENDA MOORE CT
CONTRACTOR : BULLOCK BUILDERS INC KEITH
OWNER . . : ATKINS PLACE LLC #6
PARCEL . . : 08-0653- - -0030- -23-
APPL NUMBER: 06-50015746 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 6. 401N FROM
LILLINGTON LEFT ON CHALYBEATE RD LEFT
ON DEXTERFIELD DR LOT ON LEFT.
-A.DRIGGERS

SUBDIV: DEXTERFIELD
PHONE : (919) 639-7424
PHONE :

STRUCTURE: 000 000 60X60 3BR SFD
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/04/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001285188
	10/04/06	AP	
B103 01	10/16/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001291872
	10/16/06	AE	bolt missing on rear wall near right rear corner of house. Have mason install bolt before floor framing
A814 01	10/19/06	TI	ADDRESS CONFIRMATION VRU #: 001291881
	10/16/06	AP	131 BRENDA MOORE CT LOT 23
B105 01	11/02/06	BS	R*OPEN FLOOR VRU #: 001302389
	11/02/06	AP	
R425 01	11/22/06	TI	FOUR TRADE ROUGH IN VRU #: 001312467
	11/22/06	CA	
R425 02	11/27/06	BS	FOUR TRADE ROUGH IN VRU #: 001313022
	11/27/06	DA	1. Triple LVLs must be nailed from both sides. 2. Add jacks under double above entry to hall bedrooms. 3. Nail OSB blocking in all corners. 4. Connect bath fan vents. 5. No roof boots. 6. Improper headroom at top of stairs. 6. Install and test fireplace. 7. Flash rear porch. ok to side
R125 01	11/29/06	TI	ONE TRADE ROUGH IN VRU #: 001314937
	<u>11/29/06</u>	<u>APBS</u>	

----- COMMENTS AND NOTES -----

ADDRESS . . : 131 BRENDAMOORE CT
 CONTRACTOR : BULLOCK BUILDERS INC KEITH
 OWNER . . . : ATKINS PLACE LLC #6
 PARCEL . . . : 08-0653- - -0030- -23-
 APPL NUMBER: 06-50015746 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : DEXTERFIELD LOT 6. 401N FROM
 LILLINGTON LEFT ON CHALYBEATE RD LEFT
 ON DEXTERFIELD DR LOT ON LEFT.
 -A.DRIGGERS

STRUCTURE: 000 000 60X60 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/04/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001285188
	10/04/06	AP	
B103 01	10/16/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001291872
	10/16/06	AE	bolt missing on rear wall near right rear corner of house. Have mason install bolt before floor framing
A814 01	10/19/06	TI	ADDRESS CONFIRMATION VRU #: 001291881
	10/16/06	AP	131 BRENDAMORE CT LOT 23
B105 01	11/02/06	BS	R*OPEN FLOOR VRU #: 001302389
	11/02/06	AP	
R425 01	11/22/06	TI	FOUR TRADE ROUGH IN VRU #: 001312467
	11/22/06	CA	
R425 02	11/27/06	BS	FOUR TRADE ROUGH IN VRU #: 001313022
	11/27/06	DA	1. Triple LVLs must be nailed from both sides. 2. Add jacks under double above entry to hall bedrooms. 3. Nail OSB blocking in all corners 4. Connect bath fan vents. 5. No roof boots. 5. Improper headroom at top of stairs. 6. Install and test fireplace. 7. Flash rear porch. ok to side
R125 01	11/29/06	BS	ONE TRADE ROUGH IN VRU #: 001314937
	11/29/06	AP	
I129 01	12/01/06	TI	R*INSULATION INSPECTION VRU #: 001316622

12-01-06 ARBS

COMMENTS AND NOTES

ADDRESS : 131 BRENDAMOORE CT SUBDIV: DEXTERFIELD
 CONTRACTOR : BULLOCK BUILDERS INC KEITH PHONE : (919) 639-7424
 OWNER : ATKINS PLACE LLC #6 PHONE :
 PARCEL : 08-0653- - -0030- -23-
 APPL NUMBER: 06-50015746 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : DEXTERFIELD LOT 6. 401N FROM
 LILLINGTON LEFT ON CHALYBEATE RD LEFT
 ON DEXTERFIELD DR LOT ON LEFT.
 -A.DRIGGERS

STRUCTURE: 000 000 60X60 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	10/04/06	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001285188
	10/04/06	AP	
B103 01	10/16/06	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001291872
	10/16/06	AE	bolt missing on rear wall near right rear corner of house. Have mason install bolt before floor framing
A814 01	10/19/06	TI	ADDRESS CONFIRMATION VRU #: 001291881
	10/16/06	AP	131 BRENDAMOORE CT LOT 23
B105 01	11/02/06	BS	R*OPEN FLOOR VRU #: 001302389
	11/02/06	AP	
R425 01	11/22/06	TI	FOUR TRADE ROUGH IN VRU #: 001312467
	11/22/06	CA	
R425 02	11/27/06	BS	FOUR TRADE ROUGH IN VRU #: 001313022
	11/27/06	DA	1. Triple LVLs must be nailed from both sides. 2. Add jacks under double above entry to hall bedrooms. 3. Nail OSB blocking in all corners 4. Connect bath fan vents. 5. No roof boots. 5. Improper headroom at top of stairs. 6. Install and test fireplace. 7. Flash rear porch. ok to side
R125 01	11/29/06	BS	ONE TRADE ROUGH IN VRU #: 001314937
	11/29/06	AP	
I129 01	12/01/06	BS	R*INSULATION INSPECTION VRU #: 001316622
	12/01/06	AP	
H824 01	12/18/06	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001326446
	12/18/06	AP	
R425 03	1/24/07	TI	FOUR TRADE ROUGH IN VRU #: 001342434
	1/24/07	CA	
R429 01	1/24/07	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 001343060

1-24-07 *APBS*

COMMENTS AND NOTES

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Type of Construction: II

Owner of Building: Keith Bullock Builders

Building Address: 131 Brentwood Ct

Zoning District: _____

Zoning Permit No.: N/A

Conditional Use Permit No.: _____

Building Permit No.: 06-5-15746

Electrical Permit No.: 06-5-15746

Insulation Permit No.: 06-5-15746

Plumbing Permit No.: 06-5-15746

Mech. Permit No.: 06-5-15746

Envir. C.O. No.: _____

Date: 1-24-07
Brad Sutton

Building Official

Zoning Official