

ADDRESS . : 31 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . : SHAW A LIMITED PARTNERSHIP#44
PARCEL . . : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
210S 10MILES RIGHT ONTO 1144 LEFT ONTO
1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
SOUTH DAKOTA LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 47X38 4BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 <u>5-24</u>	TI <u>DP</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249

COMMENTS AND NOTES

TP
+ grade stakes.

ADDRESS . . : 31 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . . : SHAW A LIMITED PARTNERSHIP#44
PARCEL . . . : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
210S 10MILES RIGHT ONTO 1144 LEFT ONTO
1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
SOUTH DAKOTA LOT ON LEFT. JDAVIS

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE : (910) 483-2904

STRUCTURE: 000 000 47X38 4BR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07	TI <i>AP JH</i>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692

----- COMMENTS AND NOTES -----

ADDRESS . . : 31 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . . : SHAW A LIMITED PARTNERSHIP#44
PARCEL . . . : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
210S 10MILES RIGHT ONTO 1144 LEFT ONTO
1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
SOUTH DAKOTA LOT ON LEFT. JDAVIS

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE : (910) 483-2904

STRUCTURE: 000 000 47X38 4BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07	TI	ADDRESS CONFIRMATION VRU #: 001421825
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396

AP JU

COMMENTS AND NOTES

ADDRESS . : 31 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
OWNER . . : SHAW A LIMITED PARTNERSHIP#44 PHONE : (910) 483-2904
PARCEL . . : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
210S 10MILES RIGHT ONTO 1144 LEFT ONTO
1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
SOUTH DAKOTA LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 47X38 4BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07	TI	R*OPEN FLOOR VRU #: 001428721

AP. MJ

----- COMMENTS AND NOTES -----

ADDRESS . : 31 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
OWNER . . : SHAW A LIMITED PARTNERSHIP#44 PHONE : (910) 483-2904
PARCEL . . : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
210S 10MILES RIGHT ONTO 1144 LEFT ONTO
1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
SOUTH DAKOTA LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 47X38 4BR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07 6/14/07	MR AP	R*OPEN FLOOR VRU #: 001428721
R425 01	7/11/07	TI	FOUR TRADE ROUGH IN VRU #: 001442923

Op JH

COMMENTS AND NOTES

ADDRESS : 31 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP#44
 PARCEL : 01-0536-01- -0111- -15-
 APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
 210S 10MILES RIGHT ONTO 1144 LEFT ONTO
 1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
 SOUTH DAKOTA LOT ON LEFT. JDAVIS

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE : (910) 483-2904

STRUCTURE: 000 000 47X38 4BR
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07 6/14/07	MR AP	R*OPEN FLOOR VRU #: 001428721
R425 01	7/11/07 7/11/07	JH DP	FOUR TRADE ROUGH IN VRU #: 001442923 X) Missing hanger for floor truss in garage @ door. X) Need paper work for all floor & roof truss. X) Need to replace anchor bolt in garage to right @ door. X) Missing fire caulk @ top plate to left of kitchen window. X) Leak in 2" 45o pipe fitting @ kitchen window, retest drain X) Bath exhaust fans need to be vented to outside. X) Nail guard on 14/3 wire in living room. X) Receptacle in master bedroom needs to be fastened to stud. X) Bond faucet on hydromassage tub to motor in master bathroom. 10) Gabel roof truss needs T bracing per truss drawings. 11) Washer drain 3" at first horizontal.
R427 01	7/16/07	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001446210 need 3" Head Water on drain pipes

COMMENTS AND NOTES

Because of pipes changed

ADDRESS : 31 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
 CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
 OWNER : SHAW A LIMITED PARTNERSHIP#44 PHONE : (910) 483-2904
 PARCEL : 01-0536-01- -0111- -15-
 APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
 210S 10MILES RIGHT ONTO 1144 LEFT ONTO
 1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
 SOUTH DAKOTA LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 47X38 4BR
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07 6/14/07	MR AP	R*OPEN FLOOR VRU #: 001428721
R425 01	7/11/07 7/11/07	JH DP	FOUR TRADE ROUGH IN VRU #: 001442923 1)Missing hanger for floor truss in garage @ door. 2)Need paper work for all floor & roof truss. 3)Need to replace anchor bolt in garage to right @ door. 4)Missing fire caulk @ top plate to left of kitchen window. 5)Leak in 2" 45o pipe fitting @ kitchen window, retest drain 6)Bath exhaust fans need to be vented to outside. 7)Nail guard on 14/3 wire in living room. 8)Receptacle in master bedroom needs to be fastened to stud. 9)Bond faucet on hydromassage tub to motor in master bathroom. 10)Gabel roof truss needs T bracing per truss drawings. 11)Washer drain 3" at first horizontal.
R427 01	7/16/07 7/16/07	JH DA	FOUR TRADE ROUGH IN >2500 VRU #: 001446210 Need to retest drain lines with 3' head of water for pipe that had to be replaced.
R425 02	7/18/07	TI AP JH	FOUR TRADE ROUGH IN VRU #: 001448357

COMMENTS AND NOTES

ADDRESS : 31 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
 CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
 OWNER : SHAW A LIMITED PARTNERSHIP#44 PHONE : (910) 483-2904
 PARCEL : 01-0536-01- -0111- -15-
 APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
 210S 10MILES RIGHT ONTO 1144 LEFT ONTO
 1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
 SOUTH DAKOTA LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 47X38 4BR
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07 6/14/07	MR AP	R*OPEN FLOOR VRU #: 001428721
R425 01	7/11/07 7/11/07	JH DP	FOUR TRADE ROUGH IN VRU #: 001442923 1)Missing hanger for floor truss in garage @ door. 2)Need paper work for all floor & roof truss. 3)Need to replace anchor bolt in garage to right @ door. 4)Missing fire caulk @ top plate to left of kitchen window. 5)Leak in 2" 45o pipe fitting @ kitchen window, retest drain 6)Bath exhaust fans need to be vented to outside. 7)Nail guard on 14/3 wire in living room. 8)Receptacle in master bedroom needs to be fastened to stud. 9)Bond faucet on hydromassage tub to motor in master bathroom. 10)Gabel roof truss needs T bracing per truss drawings. 11)Washer drain 3" at first horizontal.
R427 01	7/16/07 7/16/07	JH DA	FOUR TRADE ROUGH IN >2500 VRU #: 001446210 Need to retest drain lines with 3' head of water for pipe that had to be replaced.
R425 02	7/18/07 7/18/07	JH AP	FOUR TRADE ROUGH IN VRU #: 001448357
I129 01	7/24/07	TI	R*INSULATION INSPECTION VRU #: 001452261

7/24/07 JAP DT

COMMENTS AND NOTES

ADDRESS : 31 SOUTH DAKOTA CT
 CONTRACTOR : SHAW CONSTRUCTION CO INC
 OWNER : SHAW A LIMITED PARTNERSHIP#44
 PARCEL : 01-0536-01- -0111- -15-
 APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
 210S 10MILES RIGHT ONTO 1144 LEFT ONTO
 1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
 SOUTH DAKOTA LOT ON LEFT. JDAVIS

SUBDIV: SIERRA VILLAGE@OVERHILLS
 PHONE : (910) 893-4322
 PHONE : (910) 483-2904

STRUCTURE: 000 000 47X38 4BR

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 ✓ 31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07 6/14/07	MR AP	R*OPEN FLOOR VRU #: 001428721
R425 01	7/11/07 7/11/07	JH DP	FOUR TRADE ROUGH IN VRU #: 001442923 1)Missing hanger for floor truss in garage @ door. 2)Need paper work for all floor & roof truss. 3)Need to replace anchor bolt in garage to right @ door. 4)Missing fire caulk @ top plate to left of kitchen window. 5)Leak in 2" 45o pipe fitting @ kitchen window, retest drain 6)Bath exhaust fans need to be vented to outside. 7)Nail guard on 14/3 wire in living room. 8)Receptacle in master bedroom needs to be fastened to stud. 9)Bond faucet on hydromassage tub to motor in master bathroom. 10)Gabel roof truss needs T bracing per truss drawings. 11)Washer drain 3" at first horizontal.
R427 01	7/16/07 7/16/07	JH DA	FOUR TRADE ROUGH IN >2500 VRU #: 001446210 Need to retest drain lines with 3' head of water for pipe that had to be replaced.
R425 02	7/18/07 7/18/07	JH AP	FOUR TRADE ROUGH IN VRU #: 001448357
I129 01	7/24/07 7/24/07	DT AP	R*INSULATION INSPECTION VRU #: 001452261
H824 01	12/11/07 12/11/07	OT AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001536556
R429 01	7/22/08 7/22/08	TI CA	FOUR TRADE FINAL VRU #: 001645991

ADDRESS . . : 31 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . . : SHAW A LIMITED PARTNERSHIP#44
PARCEL . . . : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE : (910) 483-2904

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 02	10/17/08	TI <i>DA JB</i>	FOUR TRADE FINAL VRU #: 001691994 <i>House locked</i>

COMMENTS AND NOTES

ADDRESS : 31 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
 CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
 OWNER : SHAW A LIMITED PARTNERSHIP#44 PHONE : (910) 483-2904
 PARCEL : 01-0536-01- -0111- -15-
 APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
 210S 10MILES RIGHT ONTO 1144 LEFT ONTO
 1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
 SOUTH DAKOTA LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 47X38 4BR
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07 6/14/07	MR AP	R*OPEN FLOOR VRU #: 001428721
R425 01	7/11/07 7/11/07	JH DP	FOUR TRADE ROUGH IN VRU #: 001442923 1)Missing hanger for floor truss in garage @ door. 2)Need paper work for all floor & roof truss. 3)Need to replace anchor bolt in garage to right @ door. 4)Missing fire caulk @ top plate to left of kitchen window. 5)Leak in 2" 45o pipe fitting @ kitchen window, retest drain 6)Bath exhaust fans need to be vented to outside. 7)Nail guard on 14/3 wire in living room. 8)Receptacle in master bedroom needs to be fastened to stud. 9)Bond faucet on hydromassage tub to motor in master bathroom. 10)Gabel roof truss needs T bracing per truss drawings. 11)Washer drain 3" at first horizontal.
R427 01	7/16/07 7/16/07	JH DA	FOUR TRADE ROUGH IN >2500 VRU #: 001446210 Need to retest drain lines with 3' head of water for pipe that had to be replaced.
R425 02	7/18/07 7/18/07	JH AP	FOUR TRADE ROUGH IN VRU #: 001448357
I129 01	7/24/07 7/24/07	DT AP	R*INSULATION INSPECTION VRU #: 001452261
H824 01	12/11/07 12/11/07	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001536556
R429 01	7/22/08	TI	FOUR TRADE FINAL VRU #: 001645991

ADDRESS . . : 31 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . . : SHAW A LIMITED PARTNERSHIP#44
PARCEL . . . : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE : (910) 483-2904

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	7/22/08	CA	
R429 02	10/17/08	JH	FOUR TRADE FINAL VRU #: 001691994
	10/17/08	DA	house locked
R431 01	10/21/08	TI	FOUR TRADE FINAL >2500 VRU #: 001694520

DP-MR

----- COMMENTS AND NOTES -----

ADDRESS : 31 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
 CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
 OWNER : SHAW A LIMITED PARTNERSHIP#44 PHONE : (910) 483-2904
 PARCEL : 01-0536-01- -0111- -15-
 APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
 210S 10MILES RIGHT ONTO 1144 LEFT ONTO
 1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
 SOUTH DAKOTA LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 47X38 4BR

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07 6/14/07	MR AP	R*OPEN FLOOR VRU #: 001428721
R425 01	7/11/07 7/11/07	JH DP	FOUR TRADE ROUGH IN VRU #: 001442923 1)Missing hanger for floor truss in garage @ door. 2)Need paper work for all floor & roof truss. 3)Need to replace anchor bolt in garage to right @ door. 4)Missing fire caulk @ top plate to left of kitchen window. 5)Leak in 2" 45o pipe fitting @ kitchen window, retest drain 6)Bath exhaust fans need to be vented to outside. 7)Nail guard on 14/3 wire in living room. 8)Receptacle in master bedroom needs to be fastened to stud. 9)Bond faucet on hydromassage tub to motor in master bathroom. 10)Gabel roof truss needs T bracing per truss drawings. 11)Washer drain 3" at first horizontal.
R427 01	7/16/07 7/16/07	JH DA	FOUR TRADE ROUGH IN >2500 VRU #: 001446210 Need to retest drain lines with 3' head of water for pipe that had to be replaced.
R425 02	7/18/07 7/18/07	JH AP	FOUR TRADE ROUGH IN VRU #: 001448357
I129 01	7/24/07 7/24/07	DT AP	R*INSULATION INSPECTION VRU #: 001452261
H824 01	12/11/07 12/11/07	OT AP	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001536556
R429 01	7/22/08 7/22/08	TI CA	FOUR TRADE FINAL VRU #: 001645991

ADDRESS . . : 31 SOUTH DAKOTA CT
CONTRACTOR : SHAW CONSTRUCTION CO INC
OWNER . . . : SHAW A LIMITED PARTNERSHIP#44
PARCEL . . . : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)

SUBDIV: SIERRA VILLAGE@OVERHILLS
PHONE : (910) 893-4322
PHONE : (910) 483-2904

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 02	10/17/08	JH	FOUR TRADE FINAL VRU #: 001691994
	10/17/08	DA	house locked
R431 01	10/21/08	MR	FOUR TRADE FINAL >2500 VRU #: 001694520
	10/21/08	DP	1. run secondary drain under house to outside of foundation 2. house numbers do not contrast with wall enough 3. install water meter 4. install insulation under house 5. provide ladder for attic inspection 6. install water heater on stand
R429 03	10/28/08	TI	FOUR TRADE FINAL VRU #: 001698000

_____ *Op JH*

----- COMMENTS AND NOTES -----

ADDRESS : 31 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
 CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
 OWNER : SHAW A LIMITED PARTNERSHIP#44 PHONE : (910) 483-2904
 PARCEL : 01-0536-01- -0111- -15-
 APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : SIERRA VILLAGE @ OVERHILLS #44
 210S 10MILES RIGHT ONTO 1144 LEFT ONTO
 1120 LEFT ONTO SIERRA TRIAL RIGHT ONTO
 SOUTH DAKOTA LOT ON LEFT. JDAVIS

STRUCTURE: 000 000 47X38 4BR
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	5/24/07 5/24/07	KS DP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001415249 grade stakes for piers at less than 8 inches. T-pole receptacle box not secured and need to secure post
B101 02	5/29/07 5/29/07	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001416692
A814 01	6/05/07 6/07/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001421825 ✓31 south dakota ct
B103 01	6/07/07 6/07/07	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001423623
B103 02	6/08/07 6/08/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001425396
B105 01	6/14/07 6/14/07	MR AP	R*OPEN FLOOR VRU #: 001428721
R425 01	7/11/07 7/11/07	JH DP	FOUR TRADE ROUGH IN VRU #: 001442923 1)Missing hanger for floor truss in garage @ door. 2)Need paper work for all floor & roof truss. 3)Need to replace anchor bolt in garage to right @ door. 4)Missing fire caulk @ top plate to left of kitchen window. 5)Leak in 2" 45o pipe fitting @ kitchen window, retest drain 6)Bath exhaust fans need to be vented to outside. 7)Nail guard on 14/3 wire in living room. 8)Receptacle in master bedroom needs to be fastened to stud. 9)Bond faucet on hydromassage tub to motor in master bathroom. 10)Gabel roof truss needs T bracing per truss drawings. 11)Washer drain 3" at first horizontal.
R427 01	7/16/07 7/16/07	JH DA	FOUR TRADE ROUGH IN >2500 VRU #: 001446210 Need to retest drain lines with 3' head of water for pipe that had to be replaced.
R425 02	7/18/07 7/18/07	JH AP	FOUR TRADE ROUGH IN VRU #: 001448357
I129 01	7/24/07 7/24/07	DT AP	R*INSULATION INSPECTION VRU #: 001452261
H824 01	12/11/07 12/11/07	OT AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001536556
R429 01	7/22/08	TI	FOUR TRADE FINAL VRU #: 001645991

ADDRESS : 31 SOUTH DAKOTA CT SUBDIV: SIERRA VILLAGE@OVERHILLS
CONTRACTOR : SHAW CONSTRUCTION CO INC PHONE : (910) 893-4322
OWNER : SHAW A LIMITED PARTNERSHIP#44 PHONE : (910) 483-2904
PARCEL : 01-0536-01- -0111- -15-
APPL NUMBER: 06-50016382 CP NEW RESIDENTIAL (SFD)

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
	7/22/08	CA	
R429 02	10/17/08	JH	FOUR TRADE FINAL VRU #: 001691994
	10/17/08	DA	house locked
R431 01	10/21/08	MR	FOUR TRADE FINAL >2500 VRU #: 001694520
	10/21/08	DP	1.run secondary drain under house to outside of foundation 2. house numbers do not contrast with wall enough 3. install water meter 4. install insulation under house 5. provide ladder for attic inspection 6. install water heater on stand
R429 03	10/28/08	JH	FOUR TRADE FINAL VRU #: 001698000
	10/28/08	DP	1)Need an unobstructed path to unit in attic 24' wide. 2)Need water on house for final inspection. 3)Need 100 percent 6mill poly under house & need to remove all trash from under house.
R431 02	10/30/08	TI	FOUR TRADE FINAL >2500 VRU #: 001699370
	10/30/08	CA	
R431 03	11/04/08	TI	FOUR TRADE FINAL >2500 VRU #: 001700137

AP JH

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Owner: Shaw construction

911 Address: 31 South Dakota

State: _____ Zip Code: _____

Date: 11-4-08

Building Official

PERMIT NUMBERS

Building Permit No.: _____

Electrical Permit No.: _____

Insulation Permit No.: _____

Plumbing Permit No.: _____

Mech. Permit No.: _____

MFG. Home: _____

06-50016382

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD

Owner: Shaw Construction

911 Address: 31 South Dakota

State: _____ Zip Code: _____

Date: 11-4-08
James V. Smith
Building Official

PERMIT NUMBERS

Building Permit No.: _____

Electrical Permit No.: _____

Insulation Permit No.: _____

Plumbing Permit No.: _____

Mech. Permit No.: _____

MFG. Home: _____

06-50016387