


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

APPLICANT NAME _____

DATE _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-34"	0-40"	0-26"	0-24"						
Texture Group	.1941(A)(1)	SL	SL	SL	SL						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 2 DEPTH		34" +	40" +	26" +	24" +						
Texture Group	.1941(A)(1)	ROCK	ROCK	ROCK	ROCK						
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	—	—	—							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948	S	S	S							
LONG TERM ACCEPTANCE RATE	.1955	.8	.8	.8							



- 3 x 50' lines
- met on-site
- remove large trees
- 18"-22" ditches
- need to lay out
- might more driveway
- contracts met on-site to verify depth
- 12" ditch
- 6" corrugated
- 3 x 60' line